

# TAP200 Firmware Downloads

[Main Page](#) > [TAP Access Points](#) > [TAP200](#) > **TAP200 Firmware Downloads**

---

This page contains firmware files for TAP200 devices. Look to the table below or the [changelog](#) to find download links.

To upgrade firmware using WebUI, follow the instructions in [TAP200 Firmware](#).

## TAP200

File	Type	Release date	Size	MD5	Changelog
<a href="#">TAP200_R_00.07.07.3_WEBUI.bin</a>	Latest FW	2024.06.25	9.69 MB	316a2b23f285849af9c58d6e12a9fada	<a href="#">Link</a>
<a href="#">TAP200_R_00.07.06.10_WEBUI.bin</a>	Mass production FW	2024.04.04	9.56 MB	fc68428d4dc7b8250fbd4ac025101ad2	<a href="#">Link</a>
<a href="#">TAP200_R_GPL_00.07.07.3.tar.gz</a>	SDK	2024.06.25	30.11 MB	2a9bed67109b395e4b6a622e52285f34	

## FW checksums

---

Checksums for firmware files can be found [here](#).

## Changelog

### [TAP200\\_R\\_00.07.07.3](#) | 2024.06.25

- **Fix**
  - **Network**
    - WebUI: fixed port advertisement change
  - **System**
    - FOTA: fixed config when upgrading from older firmware with keep settings
- **CVE Patches**
  - CVE-2024-31950
  - CVE-2024-31951

---

### [TAP200\\_R\\_00.07.07.2](#) | 2024.06.12

- **Improvements**
  - **Services**
    - Wireless: removed unnecessary information from system logs
  - **System**
    - SSH: removed weak SSH algorithms
- **Fix**

- **System**
    - IP Block: fixed blocking of UDP traffic
    - Ledman: fixed WiFi LED indication when WiFi configuration is changed
  - **CVE Patches**
    - CVE-2024-31948
- 

## [TAP200\\_R\\_00.07.07.1](#) | 2024.05.03

---

- **New**
  - **Network**
    - Wireless: added mesh support
  - **System**
    - WebUI: added the ability to generate random passwords for password input fields
    - WebUI: added reset to “Factory defaults” option
    - System: changed firmware certificate verification tool
    - IP Block: added time-based login attempt blocking
    - WebUI: added firmware update notification support
    - Logging: added multiple remote syslog servers support
- **Improvements**
  - **Services**
    - WebUI: moved licenses to footer
  - **System**
    - WebUI: adjusted responsive design breakpoints
    - WebUI: added more strict password requirements for restoring backup
    - WebUI: changed firmware update option to server as a default option
    - WebUI: improved first login password change logic
    - GPL: added offline package preparation command for GPL builds
    - Kernel: updated version to 5.10.210
    - Libcap: updated package version to 2.69
- **Fix**
  - **System**
    - WebUI: fixed an issue when a user was not logged out after changing profiles
    - CLI: fixed enter key issue on mobile chromium based browsers
- **CVE Patches**
  - CVE-2022-4603
  - CVE-2022-23308
  - CVE 2022-45061
  - CVE-2023-0466
  - CVE-2023-6129
  - CVE-2023-7042
  - CVE 2023-24329
  - CVE 2023-27043
  - CVE-2023-31083
  - CVE-2023-42366
  - CVE-2023-46218
  - CVE-2023-46219
  - CVE-2023-46752

- CVE-2023-46753
- CVE-2023-48795
- CVE-2024-2397
- CVE-2024-25062
- CVE-2024-27913
- CVE-2024-22365

## [TAP200\\_R\\_00.07.06.10](#) | 2024.04.04

---

- Global changelog for **R\_00.07.06.10** - [LINK](#)

## [TAP200\\_R\\_00.07.06.8](#) | 2024.03.25

---

- Firmware **R\_00.07.06.8** was removed due to an issue with inefficient memory allocation for LED control.

## [TAP200\\_R\\_00.07.06.6](#) | 2024.03.04

---

- Global changelog for **R\_00.07.06.6** - [LINK](#)

## [TAP200\\_R\\_00.07.06.5](#) | 2024.02.21

---

- Global changelog for **R\_00.07.06.5** - [LINK](#)

## [TAP200\\_R\\_00.07.06.3](#) | 2024.01.17

---

- Global changelog for **R\_00.07.06.3** - [LINK](#)

## [TAP200\\_R\\_00.07.06.1](#) | 2024.01.04

- **Fix**
  - **Services**
    - Fixed issue with NTPclient zombie processes

## [TAP200\\_R\\_00.07.06](#) | 2023.12.20

- **New**
  - **Network**
    - Added 802.11v BSS Transition Management and 802.11k Radio Resource Measurement
  - **WebUI**
    - Renewed user interface design
    - Added network interface name change functionality
  - **System**

- API support
- **Improvements**
  - **Network**
    - Added two radio support on one SSID in Wireless
  - **WebUI**
    - Improved Events Log page loading by adding asynchronous pagination (pasikeitė puslapiavimo logika nei prieš tai buvusi)
    - Added auto redirect after changing router's IP address or port
    - Moved device menu entry "Reboot" to header menu
  - **System**
    - Updated hostapd version to 2023-09-08
    - Updated mt76 package version to 2022-12-22
    - Updated kernel version to 5.4.259
    - Added RMS data display to generated troubleshoot
    - Added process activity load list to generated troubleshoot
- **Fix**
  - **Network**
    - Fixed ethernet link not working with some 100 Mbit switches
    - Fixed concurrent Wireless STA and AP functionality on 5 GHz band
  - **Services**
    - Added minimum free space check when saving logs to flash in Logging service
  - **WebUI**
    - Fixed side menu style issues when Japanese language is used
    - Fixed displaying of vendor names in Topology page
    - Fixed language packs being selectable when still in Package Manager queue
    - Fixed realtime graphs responsive design issues
    - Fixed wireless realtime data to show signal as unavailable with no connected clients
    - Fixed setup wizard errors in Wireless configuration page
  - **System**
    - Patched OpenSSL CVE-2023-3446
    - Patched OpenSSL CVE-2023-3817
    - Patched LibXML2 CVE-2023-39615
    - Patched LibXML2 CVE-2023-45322
    - Fixed running out of space when SSHFS is mounted in /tmp while generating troubleshoot

## [TAP200\\_R\\_00.07.05.5](#) | 2023.11.13

- **Fixes**
  - **Network**
    - Fixed ethernet link not working with some 100Mbit switches

## [TAP200\\_R\\_00.07.05.4](#) | 2023.11.09

- **Improvements**
  - **WebUI**
    - Improved asynchronous pagination in events log pages
    - Optimized Overview page load
    - Added resource loading cancellation after switching to different page

## **TAP200\_R\_00.07.05.1 | 2023.10.26**

- **New**
  - Initial firmware release