

## Product Change Notification

PCN number: PCN_TRB140_2022-05-24_EN		Date: 2022.05.24
Change description		
Change type	Ethernet Transceiver chip changed.	
Detailed description	All TRB140 devices manufactured from Q3 2022, will require firmware version TRB1_R_00.07.02 or newer for the Ethernet interface to utilize Ethernet functionality properly.  Ethernet functionality will not be supported with previous firmware versions. Custom firmware built on previous SDK versions will not support Ethernet functionality for devices manufactured starting from Q3 2022.	
Change reasons	Reducing product lead times.	
Affected products information		
All TRB140 ***** product codes are affected. No product code changes.		
Product release date	Q3 2022	
Change impact		
Risk Assessment	It is advised to test TRB1_R_00.07.02 Firmware release.	
Suggested action taken	Consider contacting your sales manager if more information is needed.	
Acknowledgement of PCN Receipt		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		