

RUT955 Package Downloads (Archive)

[Main Page](#) > [RUT Routers](#) > [RUT955](#) > **RUT955 Package Downloads (Archive)**



Contents

- [1 Latest Changes \(Archive packages\)](#)
 - [1.1 Azure IoT Hub Download](#)
 - [1.1.1 Azure IoT Hub Changelog](#)
 - [1.2 Cumulocity Download](#)
 - [1.2.1 Cumulocity Changelog](#)
 - [1.3 Cloud of Things Download](#)
 - [1.3.1 Cloud of Things Changelog](#)
 - [1.4 ThingWorx Download](#)
 - [1.4.1 ThingWorx Changelog](#)
 - [1.5 Telenor Download](#)
 - [1.5.1 Telenor Changelog](#)
 - [1.6 TR-069 Download](#)
 - [1.6.1 TR-069 Changelog](#)
 - [1.7 ZeroTier Download](#)
 - [1.7.1 ZeroTier Changelog](#)
 - [1.8 WireGuard Download](#)
 - [1.8.1 WireGuard Changelog](#)
 - [1.9 French language set Download](#)
 - [1.9.1 French language set Changelog](#)
 - [1.10 German language set Download](#)
 - [1.10.1 German language set Changelog](#)
 - [1.11 Spanish language set Download](#)
 - [1.11.1 Spanish language set Changelog](#)
 - [1.12 Japanese language set Download](#)
 - [1.12.1 Japanese language set Changelog](#)
 - [1.13 Turkish language set Download](#)
 - [1.13.1 Turkish language set Changelog](#)
 - [1.14 SNMP Download](#)
 - [1.14.1 SNMP Changelog](#)
 - [1.15 USB Tools Download](#)
 - [1.15.1 USB Tools Changelog](#)
 - [1.16 UPNP Download](#)
 - [1.16.1 UPNP Changelog](#)

Latest Changes (Archive packages)

Here you can find information about latest updates for archive packages which are used on FW version [Template:Networking rutos manual latest fw](#) and lower.

Please note: Archive Packages are not supported by firmware version **RUT9_R_00.07.00** and up.

Package	Latest version	Available from	Changelog
Azure IoT Hub	0.0.5 (Signed)	RUT9XX_R_00.06.07	System: fixed buffer problems after getting data from socket
Cumulocity	0.0.3 (Signed)	RUT9XX_R_00.06.07	Signed the package
Cloud of Things	0.0.3 (Signed)	RUT9XX_R_00.06.07	Signed the package
ThingWorx	0.0.2 (Signed)	RUT9XX_R_00.06.07	Signed the package
TR-069	1.6.5 (Signed)	RUT9XX_R_00.06.07	Signed the package
ZeroTier	1.1.17 (Signed)	RUT9XX_R_00.06.08	System: fixed service crash problems
Telenor	0.0.2 (Signed)	RUT9XX_R_00.06.07	Signed the package
WireGuard	0.0.1 (Signed)	RUT9XX_R_00.06.07	Signed the package
SNMP	5.8.7 (Signed)	RUT9XX_R_00.06.07	Signed the package
USB Tools	3.6.27 (Signed)	RUT9XX_R_00.06.07	Signed the package
UPNP	2.0.2 (Signed)	RUT9XX_R_00.06.07	Signed the package
French language set	0.0.1 (Signed)	RUT9XX_R_00.06.08	Initial package release
German language set	0.0.1 (Signed)	RUT9XX_R_00.06.08	Initial package release
Spanish language set	0.0.1 (Signed)	RUT9XX_R_00.06.08	Initial package release
Japanese language set	0.0.1 (Signed)	RUT9XX_R_00.06.08	Initial package release
Turkish language set	0.0.1 (Signed)	RUT9XX_R_00.06.08	Initial package release

Azure IoT Hub Download

Version	Available from	Download link
0.0.5 (Signed)	RUT9XX_R_00.06.07	click here
0.0.4 (Signed)	RUT9XX_R_00.06.07	click here
0.0.4	RUT9XX_R_00.06.05	click here
0.0.1	RUT9XX_R_00.06.04	click here

Azure IoT Hub Changelog

0.0.5 (Signed)

- Fixes:
System: fixed buffer problems after getting data from socket

0.0.4 (Signed)

- New features:
Signed the package

0.0.4

- New features:
Added ability to use wildcards in topics

0.0.1

- New features:
Initial package release

Cumulocity Download

Version	Available from	Download link
0.0.3 (Signed)	RUT9XX_R_00.06.07	click here
0.0.3	RUT9XX_R_00.06.06	click here
0.0.1	RUT9XX_R_00.06.05	click here

Cumulocity Changelog

0.0.3 (Signed)

- New features:
Signed the package

0.0.3

- New features:
Added ability to update firmware
Added field for push connection interval
- Fixes:
Fixed Cumulocity template

0.0.1

- New features:
Initial package release

Cloud of Things Download

Version	Available from	Download link
0.0.3 (Signed)	RUT9XX_R_00.06.07	click here
0.0.3	RUT9XX_R_00.06.06	click here
0.0.1	RUT9XX_R_00.06.05	click here

Cloud of Things Changelog

0.0.3 (Signed)

- New features:
Signed the package

0.0.3

- New features:
Added ability to update firmware
Added field for push connection interval
- Fixes:
Fixed Cloud of Things template

0.0.1

- New features:
Initial package release

ThingWorx Download

Version	Available from	Download link
0.0.2 (Signed)	RUT9XX_R_00.06.07	click here
0.0.2	RUT9XX_R_00.06.05	click here

ThingWorx Changelog

0.0.2 (Signed)

- New features:
Signed the package

0.0.2

- New features:
Initial package release

Telenor Download

Version	Available from	Download link
0.0.2 (Signed)	RUT9XX_R_00.06.07	click here
0.0.2	RUT9XX_R_00.06.05	click here

Telenor Changelog

0.0.2 (Signed)

- New features:
Signed the package

0.0.2

- New features:
Initial package release

TR-069 Download

Version	Available from	Download link
1.6.5 (Signed)	RUT9XX_R_00.06.07	click here
1.6.5	RUT9XX_R_00.06.05	click here

TR-069 Changelog

1.6.5 (Signed)

- New features:
Signed the package

1.6.5

- Fixes:
Fixed connection request url issue

1.6.4 (1.6.1)

- Fixes:
Fixed WAN type value
Fixed https support

1.6.3

- Improvements:
Removed device reboot after sending configuration from server

1.6.1

- New features:
Initial package release

ZeroTier Download

Version	Available from	Download link
1.1.17 (Signed)	RUT9XX_R_00.06.08	click here
1.1.16 (Signed)	RUT9XX_R_00.06.07	click here
1.1.16	RUT9XX_R_00.06.05	click here

ZeroTier Changelog

1.1.17 (Signed)

- Fixes:
System: fixed service crash problems

1.1.16 (Signed)

- New features:
Signed the package

1.1.16

- Fixes:
Updated package version

WireGuard Download

WireGuard must be installed only on specified firmware version!

Version	Available from	Download link
0.0.1 (Signed)	RUT9XX_R_00.06.07	click here

WireGuard Changelog

0.0.1 (Signed)

- New features:
Initial package release

French language set Download

Version	Available from	Download link
0.0.1 (Signed)	RUT9XX_R_00.06.08	click here

French language set Changelog

0.0.1 (Signed)

- New features:
Initial package release

German language set Download

Version	Available from	Download link
0.0.1 (Signed)	RUT9XX_R_00.06.08	click here

* German language has been reintroduced as part of core functionality from FW version **RUT9XX_R_00.06.08.4**.

German language set Changelog

0.0.1 (Signed)

- New features:
Initial package release

Spanish language set Download

Version	Available from	Download link
0.0.1 (Signed)	RUT9XX_R_00.06.08	click here

Spanish language set Changelog

0.0.1 (Signed)

- New features:
Initial package release

Japanese language set Download

Version	Available from	Download link
0.0.1 (Signed)	RUT9XX_R_00.06.08	click here

Japanese language set Changelog

0.0.1 (Signed)

- New features:
Initial package release

Turkish language set Download

Version	Available from	Download link
0.0.1 (Signed)	RUT9XX_R_00.06.08	click here

Turkish language set Changelog

0.0.1 (Signed)

- New features:
Initial package release

SNMP Download

Version	Available from	Download link
5.8.7 (Signed)	RUT9XX_R_00.06.07	click here

5.8.6 RUT9XX_R_00.06.05 [click here](#)

SNMP Changelog

5.8.7 (Signed)

- New features:
Signed the package

5.8.6

- Improvements:
Changed simSlot to return '1' or '2' for SIM1 or SIM2 respectively

5.8.5

- New features:
Added ICCID parameter
Added 4PIN I/O parameters

5.8.3

- Fixes:
Fixed RX, TX maximum displayed packet count

5.8.1

- Fixes:
Fixed backup issues

5.8.0

- Improvements:
Added ability to choose SNMP version

5.7.3

- New features:
Initial package release

USB Tools Download

Version	Available from	Download link
3.6.27 (Signed)	RUT9XX_R_00.06.07	click here
3.6.27	RUT9XX_R_00.06.05	click here

USB Tools Changelog

3.6.27 (Signed)

- New features:

Signed the package

3.6.27

- Improvements:
Upgraded package version

3.6.25

- New features:
Initial package release

UPNP Download

Version	Available from	Download link
2.0.2 (Signed)	RUT9XX_R_00.06.07	click here
2.0.2	RUT9XX_R_00.06.05	click here

UPNP Changelog

2.0.2 (Signed)

- New features:
Signed the package

2.0.2

- Improvements:
Upgraded package version

2.0.0

- New features:
Initial package release