

TSW202 Firmware Downloads

[Main Page](#) > [TSW Switches](#) > [TSW202](#) > **TSW202 Firmware Downloads**

This page contains firmware files for TSW202 devices. Look to the table below or the [changelog](#) to find download links.

To upgrade firmware using WebUI, follow the instructions in [TSW202 Firmware](#).

File	Type	Release date	Size	MD5	Changelog
TSW2_R_00.01.02.2_WEBUI.bin	Latest FW	2024.05.16	9.75 MB	ad10d608daccee19ee53975cbc83c94e	Link
TSW2_R_00.01.02.2_WEBUI.bin	Mass production FW	2024.05.16	9.75 MB	ad10d608daccee19ee53975cbc83c94e	Link
TSW2_R_GPL_00.01.02.2.tar.gz	SDK	2024.05.16	21.13 MB	6e948e2dfeae136dba9b017af63c3e6c	

FW checksums

Checksums for firmware files can be found [here](#).

Changelog

[TSW2_R_00.01.02.2](#) | 2024.05.16

- **New**
 - **WebUI**
 - Added customizable port names in Ports Settings page
 - **Improvements**
 - **System**
 - Updated Root CA certificates
-

[TSW2_R_00.01.02.1](#) | 2024.04.29

- **New**
 - **Network**
 - Added IGMP snooping support
 - **Services**
 - Added dynamic VLAN assignment support in Port Security
 - **WebUI**
 - Added RSTP 'Max hops' configuration option in 'Network -> Spanning Tree'
- **Fix**
 - **Network**
 - Fixed link speed configuration not applying after reboot

- **System**
 - Fixed CVE-2022-0934
 - Fixed CVE-2023-28450
 - Updated OpenSSH to 9.6p1 version to fix CVE-2023-51385
-

[TSW2_R_00.01.02](#) | 2024.02.29

- **New**
 - **Services**
 - Added Privileged Access Management (PAM) support
 - Ping reboot: Added capability to restart PoE for specific port
 - **Improvements**
 - **Network**
 - Added sysname to LLDP packets
 - **Services**
 - Improved SNMP sysName OID to set device's hostname
 - Added PDExpectedData index in Profinet
 - **Fix**
 - **Network**
 - Fixed incorrect LLDP chassis id data
 - Fixed 1000 Mbps auto negotiation
 - Fixed ethernet link not establishing via 2-pair cable
 - Fixed PoE power shutdown on reboot
 - **Services**
 - Fixed Profinet PDInterfaceAdjust record
 - Fixed Profinet issue where IP would not be set without station name
 - **System**
 - Fixed log.db rotation to prevent log partition space exhaustion
 - Fixed possible Y2K38 issue for event entries
-

[TSW2_R_00.01.01.1](#) | 2023.11.06

- **Fix**
 - **System**
 - Resolved reboot-related auto-negotiation issue affecting 1000 Mbps support
-

[TSW2_R_00.01.01](#) | 2023.10.25

- **New features**
 - Initial FW release for the TSW202 device