

Template:Networking device firmware checksum list TAP200

| FW version | MD5 checksum | SHA256 checksum |
|----------------------------|---|---|
| TAP200_R_00.07.07.3 | 316a2b23f285849af9c58d6e12a9fada | 244baf029997d591c39d5ca87c462444be0ea746e864f24bdf1cf44bfa0c9ec3 |
| TAP200_R_00.07.07.2 | dbe92e96e0e6bd51299333f8b2c6b533 | ce21f21d13b7a41812478309504cfc4b9720df099747ae9ff92afe1a28d7cc49 |
| TAP200_R_00.07.07.1 | 5454d67fbfd992e7b673a0a4e8bc1ca | 3e0ea8ef2b82290ac88cd2c60f3535e072f13e96110796d3078910d1ec006e39 |
| TAP200_R_00.07.06.10 | fc68428d4dc7b8250fbd4ac025101ad2 | c5834023b1c0edc681d58f34d5a0ad8e7dcf1472326910a4c166eebe72d95bbf |
| TAP200_R_00.07.06.8 | 8d23849a480e92e0187f6c108de07317 | 4c7ae2337441c687f3b2d215c00e2dbbd7b554a0bd80eb021986f6a768107667 |
| TAP200_R_00.07.06.6 | c9ed5400fcf88bce548315cdc74420b9 | 22151108c0ea23c62602cf5733036479dff63342afce3774b3213b2f8d029fd2 |
| TAP200_R_00.07.06.5 | b28fee215247ad992099e5e83e3dc520 | 68f48eeb894dce252774deeb50e8b62378df8393f44a5fa0b3d2612011e24b3a |
| TAP200_R_00.07.06.3 | 0dbe0e6603f403e807eeba6abed8af2e | fc4eb26e6588ef4dab6730d7d77e7026e7a196a972d32d2fe98bd502d3e7c0c6 |
| TAP200_R_00.07.06.1 | ea5ce2adb5edd1a5dc2992977d72cba2 | f253a5ba56b4282426766d654cf04d4fea947cd9e53c4869f9c007ab98284339 |
| TAP200_R_00.07.06 | 248e8f6fd85ebbcf471888f80d6ce08f | e2e609b3bd2f85d69588addf5d5362dd2886a24372165951c290eff2832164c7 |
| TAP200_R_00.07.05.5 | b9c3c8cf9a072da3ef9117fbb74f7019 | 56806e86ec6b62c95736fe65898b568ed49ac484d5674623315f0b1ba5cbbca7 |
| TAP200_R_00.07.05.4 | a2410bd0b6f984a04fec815cc4aafab8 | 862185910171b6609ff7dc2d716d3337d56e05208fbf8cff808bb5fc311fe6ff |
| TAP100_R_00.07.05.1 | 193598c3e54f57ad5ecc0f6b939e7bf4 | 596efe87c61ba745bde6ba0bbe0cc994d5c454e0c9e7dbee4d262ee9740622fd |