

Template:Networking device firmware checksum list TAP100

FW version	MD5 checksum	SHA256 checksum
TAP100_R_00.07.07.1	b40c8df7707716e359f26da9373fff93	a428f133b097f62590158f246530a92ec5ce374bfeafc6516703fc4866e42e8e
TAP100_R_00.07.06.10	cc738b7866c80c71e74bef0208dc8451	404640ad0a314a9408391aa8cc70be471a8014cf71c8916f5d5625ad411dcb61
TAP100_R_00.07.06.8	790008dbae7bf275fff20bc207e5e70e	ab08c3e7b8400187d1e5e0ef149f37e7a2004c5e8dc4bc38b305392d881b3760
TAP100_R_00.07.06.6	08017f66e740c82dbaad42033ea014c1	9eb59df4a42026e84c718e00283d297e9add3a9e128825db2327e386977b4a06
TAP100_R_00.07.06.5	a969678c86d160fb60e8a806a85f9225	c452a00a1d842fe756961e429128018f86ca9677a5891354aff16086fbcd2820
TAP100_R_00.07.06.3	696a1996cbbf35cb01926fb7866ca255	f31469d65d9987eb10d339c7fb9452430a3b6c5b908db9f9746b0cea252d345b
TAP100_R_00.07.06.1	825a1ab1f9a2148a32333fa66680f248	35101ccbb020c5a3bba4fc66431eb66be4309ba1b7a7584b00161d18116e892d
TAP100_R_00.07.06	3d9d4df4198b5be2e39d7710c1f90237	47b0d22e1d0b7dec1f93ec09d6f4569d6ddf3c30d6bc3672b3c46c8340fe3f95
TAP100_R_00.07.05.4	8066e2969a29c83bda02662fe677fc50	8b89bf09b7227cdd10ff379bcaaec8ba15b7ee985ce754f105ddb859f872473
TAP100_R_00.07.05	9ab5dc86a790ead9a515b7baeafd0d24	9b1612ba01be992eebe01be6590c4ed76562ce37a42e6ec6d5084207dff0e1d8
TAP100_R_00.07.04.5	39d1021caf6a25f5147dbf0ebcd06cfb	5e93bdbedbcbb6c0cc1f52f55f0deb9f0b62c909dacdc9b910c99322606398d7
TAP100_R_00.07.04.4	2634ca8199462694c59bf4eaded6e8a3	d4c8c5671e5c88715825ae2060a069cc928aafcacc5ab836abbaf7569cda910b
TAP100_R_00.07.04.3	92f5d59eb87fd0745a573e8aca702150	71260a45f764486137a19da5d4ccc1412b37844afe88a8f9eea5d23326c52cf3