Product Change Notification

PCN number: PCN_RUT955_2022-05-24_EN	Date: 2022.05.24

Change description	
Change type	RS232 serial interface IC and RS485 TX line control logic were changed.
Detailed description	All RUT955 devices manufactured starting from Q3 2022, will require firmware version RUT9_R_00.07.02 or newer for the RS232 and RS485 interfaces to function properly. RS232 and RS485 functionality will not be supported with previous firmware versions. Custom Firmware built on previous SDK versions you will also need RUT9_R_00.07.02 or a newer Firmware version to support RS232/RS485 functionality properly.
Change reasons	Reducing product lead times.

Affected products information	
All RUT955 ****** product codes are affected. No product code changes.	
Product release date	Q3 2022

Change impact	
Risk Assessment	It is advised to test RUT9_R_00.07.02 Firmware release.
Suggested action taken	For more detailed information please contact your sales representative.

Acknowledgement of PCN Receipt
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.