

2025.03.25: New Hardware Revision

All RUT200 devices manufactured starting from Q2 2025 will require firmware version **RUT2M_R_00.07.12.3** or newer to function properly.

PCN Number: PCN_New_Hardware_Revision_RUT200_2025_03_25_EN

Change description

Change type	Hardware
Detailed description	<p>All RUT200 devices manufactured starting from Q2 2025 will feature a new hardware revision. Devices with the updated hardware will require firmware version RUT2M_R_00.07.12.3 or newer to ensure proper functionality and compatibility. Previous firmware versions are not compatible with the new hardware revision. Disclaimer: Input/Output will not function on new hardware if firmware older than RUT2M_R_00.07.12.3 is used.</p> <p>Hardware changes:</p> <ul style="list-style-type: none">• Added option to manufacture with eSIM module• Changes related to Input/Output control
Change reasons	New hardware revision

Affected products information

Model	Affected order codes	Order code changes
RUT200	RUT200 *****	No changes
Upcoming change date	2025 Q2	

Change impact

Risk assessment	<p>All risks are firmware-related. It is strongly advised to test firmware release RUT2M_R_00.07.12.3 or newer on the updated RUT200 hardware revision devices.</p> <p>Please note: This product change notification does not affect previously manufactured RUT200 devices.</p>
Suggested implementation plan	<p>Firmware downloads for the device can be found here.</p> <p>For further information, please contact your sales representative.</p>

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification – Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.

Registration code 305579419
VAT number LT100013223510

Swedbank AB
LT78 7300 0101 6274 0111
S.W.I.F.T. HABALT22

www.teltonika-networks.com

