

## Product Change Notification

PCN number: PCN_RUT9xx_20190619_EN		Date: 2019.06.19
<b>1. Change description:</b>		
Change type	Device Flash memory changed	
Detailed description	RUT9** series Flash memory changes. Old firmware versions will not support new flash memory, meaning that only RUT9XX_R_00.06.02 and newer firmwares will work with updated hardware. Custom firmwares built on previous SDK versions will also no work.	
Change reasons	Reducing product lead times.	
<b>2. Affected products information:</b>		
All RUT9** ***** product codes are affected. No product code changes.		
Product release date:	RUT900: week 30, 2019 RUT950: week 23, 2019 RUT955: week 23, 2019	
<b>3. Change impact</b>		
Risk Assessment	All risks are firmware related. Custom SDK firmware can be re-built using these instructions: <a href="https://wiki.teltonika.lt/view/SDK:_new_flash_support_instructions">https://wiki.teltonika.lt/view/SDK:_new_flash_support_instructions</a>	
Suggested Implementation Plan	Device firmware downloads can be found at <a href="http://wiki.teltonika.lt">http://wiki.teltonika.lt</a> For more detailed information please contact your sales representative.	
<b>4. Acknowledgement of PCN Receipt</b>		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		