

# Nomenclature, classification, identification codes

[Main Page](#) > [General Information](#) > **Nomenclature, classification, identification codes**

Product	EAN code	ECCN	HTS	HS	MAC	NSN code	PCT	TAC code
BAT120	<a href="#">4779027312910</a>	<a href="#">EAR99</a>	<a href="#">8504.40.95</a>					
RUT200	<a href="#">4779051840229</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>		<a href="#">8517.6270</a>	<a href="#">RUT200 TAC codes</a>
RUT240	<a href="#">4779027312149</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-000-9390</a>	<a href="#">8517.6270</a>	<a href="#">RUT240 TAC codes</a>
RUT241	<a href="#">4779051840151</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>		<a href="#">8517.6270</a>	<a href="#">RUT241 TAC codes</a>
RUT260	<a href="#">4779051841332</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>		<a href="#">8517.6270</a>	<a href="#">RUT260 TAC codes</a>
RUT300	<a href="#">4779027312903</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>		<a href="#">8517.6270</a>	
RUT360	<a href="#">4779027312804</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-001-0521</a>	<a href="#">8517.6270</a>	<a href="#">RUT360 TAC codes</a>
RUT901	<a href="#">4779051840823</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUT901 TAC codes</a>
RUT950	<a href="#">4779027311289</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUT950 TAC codes</a>
RUT951	<a href="#">4779051840168</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>		<a href="#">8517.6270</a>	<a href="#">RUT951 TAC codes</a>
RUT955	<a href="#">4779027311302</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-000-9391</a>	<a href="#">8517.6270</a>	<a href="#">RUT955 TAC codes</a>
RUT956	<a href="#">4779051840175</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>		<a href="#">8517.6270</a>	<a href="#">RUT956 TAC codes</a>
RUTM50	<a href="#">4779051840540</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUTM50 TAC codes</a>
RUTX08	<a href="#">4779027312477</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			
RUTX09	<a href="#">4779027312460</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUTX09 TAC codes</a>
RUTX10	<a href="#">4779027312453</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			
RUTX11	<a href="#">4779027312378</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUTX11 TAC codes</a>
RUTX12	<a href="#">4779027312743</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUTX12 TAC codes</a>
RUTX14	<a href="#">4779027312965</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">RUTX14 TAC codes</a>
RUTX50	<a href="#">4779051840250</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-001-1295</a>		<a href="#">RUTX50 TAC codes</a>
RUTXR1	<a href="#">4779027312613</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-001-0522</a>		<a href="#">RUTXR1 TAC codes</a>
TCR100	<a href="#">4779027312811</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">TCR100 TAC codes</a>
TAP100	<a href="#">4779051840182</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			
TAP200	<a href="#">4779051840199</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			
OTD140	<a href="#">4779027312804</a>	<a href="#">5A991.c.10.b</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">OTD140 TAC codes</a>
TRB140	<a href="#">4779027312408</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">TRB140 TAC codes</a>
TRB141	<a href="#">4779027312620</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>				<a href="#">TRB141 TAC codes</a>
TRB142	<a href="#">4779027312385</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>				<a href="#">TRB142 TAC codes</a>
TRB143	<a href="#">4779051840137</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>				<a href="#">TRB143 TAC codes</a>
TRB145	<a href="#">4779027312415</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>				<a href="#">TRB145 TAC codes</a>
TRB245	<a href="#">4779027312750</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-001-1236</a>		<a href="#">TRB245 TAC codes</a>
TRB246	<a href="#">4779051840755</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">TRB246 TAC codes</a>
TRB255	<a href="#">4779027312767</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">TRB255 TAC codes</a>
TRB256	<a href="#">4779051840762</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>			<a href="#">TRB256 TAC codes</a>
TRB500	<a href="#">4779051840236</a>	<a href="#">5A991.c.9</a>	<a href="#">8517.62.00</a>	<a href="#">851762</a>	<a href="#">00:1E:42:*.~*.~*</a>	<a href="#">7025-47-001-1294</a>		<a href="#">TRB500 TAC codes</a>
TRM240	<a href="#">4779027312774</a>	<a href="#">5A991.b.2</a>	<a href="#">8517.62.00</a>					<a href="#">TRM240 TAC codes</a>
TRM250	<a href="#">4779027312781</a>	<a href="#">5A991.b.2</a>	<a href="#">8517.62.00</a>					<a href="#">TRM250 TAC codes</a>
TSF010	<a href="#">4779051841356</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW030	<a href="#">4779051841431</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW040	<a href="#">4779051841448</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW100	<a href="#">4779027312828</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW101	<a href="#">4779051840113</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW110	<a href="#">4779027312958</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>			<a href="#">5895-47-001-1532</a>		
TSW200	<a href="#">4779051840120</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW202	<a href="#">4779051840281</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW210	<a href="#">4779051840243</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW212	<a href="#">4779051841370</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					
TSW304	<a href="#">4779051840144</a>	<a href="#">5A991.c.10</a>	<a href="#">8517.62.00</a>					

**Disclaimer:** All nomenclature codes or other regulatory information provided herein reflect the current Teltonika interpretation of regulations and are subject to change without prior notification. It is the obligation of the exporter to comply with applicable export and import control laws and to provide classification information at the time of export/import. Teltonika makes no representation as to the accuracy or reliability of information provided, and is in no way responsible for any damages or penalties suffered by other parties as a result of using or relying upon such information.