

RUT2M Firmware checksum list



Contents

- [1 Summary](#)
- [2 Checksum list](#)

Summary

A **checksum** is a sequence of hexadecimal symbols generated after running an algorithm called a cryptographic hash function on a file. Calculating a checksum and comparing it with the one provided by the file source can be used as a file authenticity check method.

For example, if you download a file like a firmware image, you should be able to calculate that file's checksum and, if the file is authentic, the checksum should match the one provided by the file's source. If the checksums don't match, it means the file's contents were tampered with, for example, by a malicious third party attacker. This file is probably dangerous and shouldn't be trusted.

Checksum list

Firmware file checksums are listed by firmware release date, from newest to oldest (top to bottom).

FW version	MD5 checksum	SHA256 checksum
RUT2M_R_00.07.08.1	fe2591bd4fa03fec6f06c79c41c04c65	7bcdc334771a1a1b4dd616fb52a9ce26aaeed0a74055858f9323694ddc72129
RUT2M_R_00.07.08	3b823a5d36b60d043f391d5953b2a830	e338e2b290ff48903f955de877f34f53a0166b1c974e24555b2b18380a71b673
RUT2M_R_00.07.07.3	8d0b218e7ceb1c58315f67660315d668	d476b102d72a8559c57ecb4b0f8c94360083e941294eac0e2bd89f1769be622d
RUT2M_R_00.07.07.2	a2743d89a8746ea0f5d43fa3b0ba139f	ec81b1be76e632b36a2747bf3622cd0a5fcd7db194204ffbde7556a435dffe75
RUT2M_R_00.07.07.1	04896a5f2776e0134564f9a98d62e742	fc757595faeeab0e5486942b2737fd7baf1132e978558b647e801511b445e95
RUT2M_R_00.07.07	f225fff9f3b407f472ac2d5eedafb0c0	485fc169ef5f348faf4b0644e7c17530a8d90e67efe6cc8d40eccd170388cc2e
RUT2M_R_00.07.06.5	88e36fb299b412b0fa1de027d95935eb	2292af0a738d7c25023ac3dc6930a0a8772bf2190f74dfdbfdaf1b4ba2509799
RUT2M_R_00.07.06.8	fead573bf24f6c351eba0710621a88ca	a1d20fccaeef89b9e814f260a65dbbd743436f49b595d4fc1007280a23389597
RUT2M_R_00.07.06.6	c1faa8dc31a4b379ef850da7971958f2	b9bc09d2ac71fd92a26ba6c65e8cc4a9bcd8ca6185cab730ffe23cf2a9d43f
RUT2M_R_00.07.06.5	c678ce911774237740573b179b32a0	f958814a33f7e6149ed70ad95b6383fed2fc239eb1ea2b50a617daf993dc99cf
RUT2M_R_00.07.06.3	78061b795865c72a25eba405afbdffcd	d00704b2cedc00e1750a8d452261625473d77361623569113ba9f58dc7884037
RUT2M_R_00.07.06.1	e6c01ebb6fe44c3bd93ee846b3dbd352	e652e0552dba155cd9ce33b88bb2b9c5574e747cee4a0027f524e02a34ff6a2fe
RUT2M_R_00.07.06	8c7fea7f526f6bc6422aaeabc7874986	db32f9ce57fdadab00a9764012262604b5111b87bfc023e5ffa7ae6a888e2630
RUT2M_R_00.07.05.4	c73d5f3e914a38543e22208fc41f210	cdf0dc3cccd018fd474879f3839399406756beee439c6343f10970084757c80e
RUT2M_R_00.07.05	0b25cc67bdca421cadbae28c5471161f	ed970f51c6a0910c0802b54f91444c4be459cb993c062cc720c8463b59a1d9729
RUT2M_R_00.07.04.5	99dfc525f2fbb4bee6a26d4d280c3f2e	eddfdb543d8d9848179800ef53dfd9bd91b5bcebf2045c162457d28a8f02e47
RUT2M_R_00.07.04.4	334c810244ac86854cac848d1ff8f969	bbe50aee5d6a0395551c4994dfbd748d5b3c9de73eb10443484805f61d6b2350
RUT2M_R_00.07.04.3	05f073bc056113da1e832317f91988e1	aae9cfaf2f0382cee48ca67e4f671eef87ad5fd47cd449cf626982b6e7d4a8d3
RUT2M_R_00.07.04.2	795530e902f7678728688264f5ea9851	2d0ee285c6435b13f387a6fbdaf0f6d2adaddeef4ac1f4b8b7698e0c22941b29
RUT2M_R_00.07.04.1	2dbedcc491f61550211c58c42a57ef4a	5c9d469e528d50013eec0cb891ecae4379a002d7a9aa01300b5cf928c5da812
RUT2M_R_00.07.04	c884031a13c0199047e5989586911eaa	b6087bc381102a4ad4219e35f6acb2df6e7674a85b5a795a2311fd8bb42daa1b
RUT2M_R_00.07.03.4	b8f90d03e76e54f63c14a037ce998471	23517943a481b5d951b17e150c000d761440db7988d23e08c39be8654c24ea6f
RUT2M_R_00.07.03.3	42d88970a61ffd6e467e23d6614e904f	b069cec2d17e3c545dddce4d021e3f854d85d7377374c74d76a2d39bd59179eb
RUT2M_R_00.07.03.2	1e6d8f55848a00beb3ebbb06e4e56497	ddb3066d554dddea8870a6d2f79085c63b921f759e4100ff00714fc5ee76bfaf
RUT2M_R_00.07.03.1	a6f63fcc883a7d8e5105d5e4ff13c260	c62ef9feca2cf3c215384c3d845ae7c38ad2fe283f018ce9a412ebfc002d0c64
RUT2M_R_00.07.03	9e9fa214dcf27b372e523e40cda35335	2429423d80344d2d7b566b5710e63d99cfe3d4864a29f4e647602c42b17ffc4f
RUT2M_R_00.07.02.9	c884031a13c0199047e5989586911eaa	4b8894d2854f7850a628d6bb0a74adb7052ed3f1361d82c29ab289601e93aefa
RUT2M_R_00.07.02.7	5f50beac3575ddedc063ad46a0ef2f93d	2d89252930347e3755a277276528d8059858801ab7c6546e06501c5e380d6806
RUT2M_R_00.07.02.5	3d9f8aa27da9c7ecb30ecee5c66588c8	9e5aa52d6c37736117b545a966fecdf583bdec3be53611dea0657e1fcdelfa8
RUT2M_R_00.07.02.4	efab90bd37f947fa1a5e403bdf07ded0	ae0772e68d600d554caea641878b8a6a75a346e5c9ad1831f9652621528ffbd
RUT2M_R_00.07.02.3	574bd6cfff23d21b18d62db32375ceee1	ffb281db6a8347997def6597eef1c8051097d99eb9507d6df2fb05814b92210e
RUT2M_R_00.07.02.2	31e46e8ae6a458c2526848ba705664c	0a24067e4bb2182f4de068f2581649f7705b4dda5520d8265270475ceb44f00
RUT2M_R_00.07.01.4	bceb73437f7b96ca39b1617502f2eefc	b9c0d2fed8b9b23430a19e453bbd24e66dd2c81c9fa02a834fbd707c7860db5

RUT2M_R_00.07.01.3	acc638116c5986f6906d794c49481833	743282f41d3bcbb4bf5a87803f78100c3ffbb151d43fdefc1788011489a314b5
RUT2M_R_00.07.01.2	734c77671933eded76ca6656aad37eca	b8044d734d7d4e715c50fd196de1cff28ddd4ea438f310030f1950ab09af98c8