RUT850 Product Change Notifications

<u>Main Page</u> > <u>RUT Routers</u> > <u>RUT850</u> > **RUT850 Product Change Notifications**

Product change notifications (PCN) is a way of informing customers of upcoming changes related to Teltonika Networks products. This includes outward appearance adjustments, hardware improvements, changes to package contents, etc. Changes related to a product's firmware are not included in PCNs (click here to see the firmware changelog).

This page stores information regarding changes to the <u>RUT850</u> device. Below you will find a list of both upcoming and already implemented changes sorted by newest to oldest (top to bottom).

Contents

- 1 2021.02.26: end of production
- 2 2020.08.14: changes in bottom labeling
- 3 2019.06.19: device flash memory change
- 4 2018.12.04: supported LTE band changes
- <u>5 2018.11.16</u>: new top sticker

2021.02.26: end of production

Effective March 31st, 2021, it will not be possible to order RUT850 series devices.

Change description

Change type End of Production

Orders for RUT850 ****** can be placed until 2021-03-31 Detailed description

Production for RUT850 ****** shall continue up until 2021-12-31, depending on placed orders until the date specified.

Change reasons End of Production Change date 2021-02-26

Affected products

Model Removed order code Replacement order code

RUT850 All RUT850 ***** codes are affected

Change impact

1. Extra stock planning necessary, as it won't be possible to order any quantities after 2021-03-31 Risk assessment

2. All running or upcoming projects, that utilize RUT850, must be reviewed and appropriate action taken

Contact your Teltonika Networks sales manager and discuss how this change will affect your business. You should re-check your long-Suggested action taken term planning and forecasts. Please discuss with your sales manager the possibility to use a different device from the Teltonika

Networks portfolio.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.

To download the pdf version of this notification, <u>click here</u>.

2020.08.14: changes in bottom labeling

Effective 2020, week 36, RUT850 routers will be produced with modified bottom labeling/engraving.

Change description

Change type External/visual The product code will be removed from the bottom labeling/engraving. The formatting for the remaining information on the

labeling/engraving will be adjusted. Product code information will also be removed from the QR code.

The labeling on the product packaging will stay unchanged. Detailed description

Old version:

Placing product code on the product itself is misleading, product code describes what is included in the product equipment package, Change reasons

not in the product itself.

Affected products information

All RUT8** ***** product codes are affected. No product code changes.

Product release date 2020, week 36

Change impact Risk assessment

The exact product code will not be present on the product itself, the exact product code will be found on the packaging box or determined by serial number. This might impact marketing materials due to changing contents of the bottom informational laser

Suggested implementation plan No implementation plan needed

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, <u>click here</u>.

2019.06.19: device flash memory change

Effective 2019, week 28, RUT850 routers will be produced with a different type of flash memory.

Change description

Change type Device flash memory changed

RUT850 series flash memory changes

Old firmware versions will not support new flash memory, meaning that only $\underline{RUT850}\underline{R}\underline{00.01.03.4}$ and \underline{newer} firmwares will work

Reducing product

lead times.

with updated hardware

Custom firmwares built on previous SDK versions will also not work.

Detailed description

Change reasons

Affected products information

All RUT8** ****** product codes are affected. No product code changes.

Product release date 2019, week 28

Change impact

Risk assessment All risks are firmware related.

Firmware downloads for the device can be found here.

Suggested implementation plan For more detailed information please contact your sales representative.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, <u>click here</u>.

2018.12.04: supported LTE band changes

Effective February 2019, RUT850 routers will have different supported LTE bands.

Change description

Change type Different LTE band support

Supported LTE frequency band list updated: Added LTE FDD B28A (703-718/758-773 MHz) Detailed description

Removed LTE FDD/WCDMA B5

Change reasons LTE B28A support February 2019 Product release date

Affected products

Model Affected order codes Order code changes RUT850 RUT850 3***** RUT850 9*****

Change impact

Device behaviour might change due to supported band list changes Risk assessment Suggested implementation plan If any band mismatch is suspected - samples are available to order.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement

To download the pdf version of this notification, <u>click here</u>.

2018.11.16: new top sticker

Effective December 2018, week 50, RUT850 routers will be produced with a **new top sticker**.

Change description

Detailed description

Change type External/visual

Top sticker design improved

Old version:

Change reasons Visual changes

Product release date December 2018, week 50

Affected products

Model Affected order codes
RUT850 RUT850 ******0 No changes

Change impact

Risk assessment Marketing material such as photos might need replacing

Suggested implementation plan Related marketing material can be found here

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download a pdf version of this notification, <u>click here</u>.