

[https://wiki.teltonika-networks.com/view/SDK:\\_new\\_flash\\_support\\_instructions](https://wiki.teltonika-networks.com/view/SDK:_new_flash_support_instructions)

## **SDK: new flash support instructions**

[RUT230](#), [RUT240](#), [RUT850](#), [RUT900](#), [RUT950](#) and [RUT955](#) devices will be manufactured with a new type of flash memory starting from the second half of 2019 (click on one of the previous links for more details). Firmwares compiled on older than RUT2XX\_R\_00.01.07, RUT850\_R\_00.01.03.4, RUT9XX\_R\_00.06.02 SDK versions will not work with these devices, because they lack the new flash support.

To solve this issue, move the [473-mtd-m25p80-add-support-for-XTX-flash-and-undefined-flash.patch](#) file to the target `/target/linux/ar71xx/patches-3.18/` directory and re-compile the firmware.