

TRB500 Firmware checksum list



Contents

- [1 Summary](#)
- [2 Checksum list](#)

Summary

A **checksum** is a sequence of hexadecimal symbols generated after running an algorithm called a cryptographic hash function on a file. Calculating a checksum and comparing it with the one provided by the file source can be used as a file authenticity check method.

For example, if you download a file like a firmware image, you should be able to calculate that file's checksum and, if the file is authentic, the checksum should match the one provided by the file's source. If the checksums don't match, it means the file's contents were tampered with, for example, by a malicious third party attacker. This file is probably dangerous and shouldn't be trusted.

Checksum list

Firmware file checksums are listed by firmware release date, from newest to oldest (top to bottom).

FW version	MD5 checksum	SHA256 checksum
TRB500_R_00.07.07.3	7bbe71497aeda6f10ade1077f5316f07	8f83ac1fbf0de49ba04ef21ce4276a1e716a3794708e680ae5ef5a8dcb8c5f76
TRB500_R_00.07.07.2	9a10c49f728d6033c2dd20a50cd2cad6	f191c7dbb290e7ea53162d8eeb866b43d6a698fb7573e1c1352c90384e387602
TRB500_R_00.07.07.1	c8620761ea5905e6e4d7890e2073bc6d	fc960e7512891e6b9a49b966951095b459833c2cf92f8ae2b825b8ab8878d00e
TRB500_R_00.07.07	939e304d280151788585b73e3c504685	1f6b07c48025fb8dad92dda527a408ca128346844e4940f87b9b978d7f5647a1
TRB500_R_00.07.06.10	f2702f32265086425e4214bd24f53da1	c3b81215b321cf8a59ae1089bccd0a3379a0659e575f333cb2e268199a007abf
TRB500_R_00.07.06.8	b4b58d5d019c677fad2b7661d4692c0b	8baaff4df370fd065cc0219c6b1c16812ba8561a3b7d9c089db13417e327e338
TRB500_R_00.07.06.6	b10b53ed10144a24246a3fd5103f6a6f	07f431fd87be39bb79ddf2974127f4fdfed52ee376beb3987b84103e8419797c
TRB500_R_00.07.06.5	9e05acfe0d4a5eac13f664a35035b4fc	2ab3f65b237c75f8a1737ff6a0cf8e9b4f902073d88efdeb233b3b9dc30c6f27
TRB500_R_00.07.06.3	1eb84791e86e8b4e5acd8f38dc49ce86	7705af72f1c9372f1d9a94b6cb809f84add06f2c8404e76e5b403a4e0160f47
TRB5_R_00.07.06.3	1eb84791e86e8b4e5acd8f38dc49ce86	7705af72f1c9372f1d9a94b6cb809f84add06f2c8404e76e5b403a4e0160f47
TRB5_R_00.07.06	b9a97a5b5499e524922ca1721a93a4bb	2ea25c74950c4651d3d5f49b93985d8bcc25d59064b71975453f1767ed5a2580
TRB5_R_00.07.05.4	82eba4ddad7a78d4b465710334bce570	62249a6ca7613ce640cc388da2caf1aa853030b1a7584e751b4b7673e1426628
TRB5_R_00.07.05	dea6559ac8bc2fd2d600b2a1828ee184	4a529747cdf780cfabbf4a64f02d419a255201c0f53296beaf35a1a8540ce624
TRB5_R_00.07.04.5	7a2de7e9a00bea316a73788bf13aab19	2891398a93c07da47e5946c2ec34b82c85ad88baaac3b11aa0601f925470964b
TRB5_R_00.07.04.4	ea7376e47830f46f53c689ea29229a9c	d6505d80d3b65df8b6576dc4c28a04eb7dd8a71f3d3d45b3db24245a182b92f6
TRB5_R_00.07.04.3	f9d77392f5f397c23d2e8c43bc612306	a8f34eb8735295e401ac268d5eef4e1b4c854daa96714a2174a6499bb38882b9
TRB5_R_00.07.04.2	ab42c9c3522b7b5095021984d7cf3115	308284d1255b619b0c0e0ca1e91468bea2f3ddf705721eea03d38fdf15f6cacf
TRB5_R_00.07.04.1	c8a61c524b96dc45be194a955b049ae	6f221a23a9c3e0a1729a6050a155f5805852f5c066aca671c7ff70a23af020d2
TRB5_R_00.07.03.4	fb66c5aedb9cb93e47517dea03c7d4c2	11a2714345fa9affe08159855426e2c5a154fc36336a56f1a547eadb3ec57ac2
TRB5_R_00.07.03.2	85f1d515f5a52aba964e57814e841d2e	b5f9c5d9c540471870eddcfca5377bc23708489c6764ebac850b69cf605d117b
TRB5_R_00.07.03.1	c36aed5ad805637d60f281f4ea023184	15af9c1a44efc84bd2daa873558e2ba00c61ef81e472a3df725f39affc87021
TRB5_R_00.07.03	afc6f4b031507ffa63bf8487b7aa8	b6fafee5ab63dae8123adfa188d3abb4cd46948d1b5c632bfc8467f635e4565
TRB5_R_00.07.02.8	08e3bfa6a8761768473b3fa533827e8b	dfbe757ba2044eccdb81289c9e763d43b740041caaba0e02c884386d9e27d1c4