

Template:Networking device firmware checksum list RUT30X

FW version	MD5 checksum	SHA256 checksum
RUT30X_R_00.07.07.3	e0901b59816b03045a07069f5b2ae1fa	317f961df8b462ace28568fe28aa60bebc72ac4fe3c6f0755f86e4efd2c231c0
RUT30X_R_00.07.07.2	50c6cc9b9080ebb77b3d148cca319f97	280cb2a3061653474e9ddef60edaedd795244d2e75edffae35816bd777fe5ff
RUT30X_R_00.07.07.1	c0216034a8be592ca724326a2e8ae3ea	1a570f8359c9800862769b23c64bf12d63d5721f1757af057036265c6b39b5ed
RUT30X_R_00.07.06.10	1c7a2958289eb77b9c66983757f114b7	8b3a0dc836756643f16f4995f60079bbb83ceec839c8688f931fdfdc22e4d4dfc
RUT30X_R_00.07.06.8	111f048a9be73b8c4e8093350b8713f8	c5831bc37480dc166519d92deb75709477b3b73b3362a2a8b7ee590e30538d05
RUT30X_R_00.07.06.6	5e791080b1fc9f5ca09215b8fb63c1c1	acf4ff6e1a93ced9f26fc0e2dfc4e44e753c26fbdaa939f8c0af04e0d2066b2b
RUT30X_R_00.07.06.5	11dfbb85cd4af4a35f3e56229b2eef95	13ff291c92eacea194fc6a6cc3b669348d6429f3970e4fa699bef2a09540065
RUT30X_R_00.07.06.3	8569659cb8bf6172101a8cbfc338ff1f	09f3d717fcfb58998059b1684096e25be3499172f1ea57a5ffffdb2fc02a5e52a
RUT30X_R_00.07.06.1	da2345edf9aab4571a00112513cdd494	968385b274e8395cb8b5c534ddf11d16976265930674a3ff4fb75642c58a98ec
RUT30X_R_00.07.06	2f459c1e401a6d300e5c18dd70ea38b4	7c6d174cd877a69ed0401b9ce772df81413852690bb14d6f011cb347fab4dbd1
RUT30X_R_00.07.05.4	b79a8ded769499a84869e439a1daee62	048773949aa679714bf26d8a185e2a97059bcfa3a410c0081e3ff8314e0686d5a
RUT30X_R_00.07.05	bb3cdc1a07f6c7de51dbace9127750d3	f28b187f47da3ac32360c04642f4ee4ee1bf7ea4f0da1f9da53e52964c464676
RUT30X_R_00.07.04.5	5decd518cdfc341fda50d727ab8be584	2e56a0133635dfc58d8be79560fe401515810f8f1acf8b327ca25f482df43f5
RUT30X_R_00.07.04.4	585e4f28ff087cdbc394a33b853d53fa	cf09e8ee926a866c6cc9567ac0347348d5a3ea4c208a515de9f29b1640e26e9c
RUT30X_R_00.07.04.3	ae61cff4bcfa2f12ea463a7784f7890d	cb98115df7d4d068c8d0c8b7e3267f45f1fbd693e7cc9eb8753164beaf5bacc
RUT30X_R_00.07.04.2	af7af44ccaba56feb81952ff592a8bd7	8b20af3fb1842c298790e11b53541eaa1913cccd4b251032bae95d5c51e3e0a30
RUT30X_R_00.07.04.1	106738dc97d769dfe5b320c69af684c1	5aa778dc91861d2a5a0c5113b1d460b5a2b6b42330c6e5ed11236126a2c3e924
RUT30X_R_00.07.04	dd64b910980e942e94df608391b24e64	13f1da8e2e51421e341b35d0ff080a49e4001588f1794a307eb9b05d777c4cc5
RUT30X_R_00.07.03.4	088ac8f10f046033e3ab6168dc99d886	3054df6e2e5c83b1582ff78db05e5d9b48c3ff5bef546f702be51a69fad434d8
RUT30X_R_00.07.03.2	19b4b19db868070a117b62a23b5bfb34	f40ef0bcb3ecf7f5ac8b82c3bd701782abeb2f9ea2d61a90a8e2f6d9605fdc6f
RUT30X_R_00.07.03.1	6e3fa5076fd742af9f47fa557ffd46b1	0ce7962c898894ce9e2dcab0bda25d3bf69e3f91ae8814baf6367dc36b0f1cbf
RUT30X_R_00.07.03	c4f30a0cb4a7e74d4fbc7fcc601766d0	fe7e549a0978ab8d2e6b787740164f895309b120f264364304b447d8e9d2ae44
RUT30X_R_00.07.02.7	43d1632a96d267b231ef96d8ab4b8377	ac5d71618e23688a1042d408950bdebe14af0b486f4aca354b86d4d2dd64394
RUT30X_R_00.07.02.6	c2bec7174ebd4807114b9726aacd7ffe	f503deff78f6aac9e6f9d66cd8c190954951be268057996846416da54f4b4122
RUT30X_R_00.07.02.5	1575e90bb4be9f239d74f0ea1c6843a8	7d444c80e3435281d9618a2abea06b849ec01e8a196ee6f3886a98020cb25ce3
RUT30X_R_00.07.02.4	875978b37b17309210a09aa7d6c2f53a	5746e9c344f8cad1535c1ff44e648a5486b23c6c2cc8ef83d3bfff07df96a592d
RUT30X_R_00.07.02.2	89dc3db485f7f1d2b91842de48319778	489f5fc255c1dd623de2cebdc11de85220a097bdeac1a0f94c67222b6848789
RUT30X_R_00.07.02.1	0f741107293285a0b661fd9ea33f82e0	fe25fa6015b206ee2463862cfb95b09241d5060193460a6564f820b871e249bc
RUT30X_R_00.07.02	dd30a5b86ace22bf05c3d67ab3099d47	dceb29bcf98725115c3a312edf45ffe783eae5a234753f7f8c5d47127f3371e6
RUT30X_R_00.07.01.4	1ef27e9f3511bf1c59b70ba379acab04	72a037728e3c5719bef18a08a1e6cbe86e610ee56f693eb94f42b3add3e85767
RUT30X_R_00.07.01.3	e0f4cb7a870e18295718595c1f8bb6b1	5784f9a6481fc0b99e7a02906e092568de63429edc4ee81990bfeb19c99122dc
RUT30X_R_00.07.01.2	b1dd18f7f62043aae3168955ad6d0456	ae69e700ba6204e0172d3164b00b981b941cfd5aeb7b75e79e752e1bd4eb55a
RUT30X_R_00.07.01	32d66e3b408858a961ef672ed591d627	be7df0731ad94ec24f215aa1d39cb7c29455ba6467df6228a6853fbb3b37f3a1
RUT30X_R_00.07.00	878d33d38a14e6e0e65550403d663076	849d3ea6069404f8413a34013097dc9b42a7373eb41eb67be3b3854cb4cbdd5b5
RUT30X_R_00.02.06.1	a72e07de483f93532fcdaba5dd702a5	309b1f20994205d4466354a6b9437105c971b413150ecd4b0abf3bbcbda779b6d
RUT30X_R_00.02.06	0e0b50b1726de57b88592913cacf997d	b023e424d3ad9c6444cddb9e849fda2410ae769273652187fe66ee45bbec6edf