

Template:Networking device firmware checksum list RUTX

FW version	MD5 checksum	SHA256 checksum
RUTX_R_00.07.08.2	96b8a17a6e41c4de9dba356f3192db1b	492dacd64fed2a2a825d8033aa4fa4fc4aede0217707da773e33210e293b24
RUTX_R_00.07.08.1	0fa0c8b4ad98e658b38424fbf2efa090	c623ea7b4a134bfc85dd051d2e4b218e2241a8eda512ac51dda1091f27edce74
RUTX_R_00.07.08	cbd1cb7561b07d942ca554f7e15945af	8ce107ccabfc4571e664b05317e639bece6e7cfc36a796fa6b6410e9d2c3c
RUTX_R_00.07.07.3	2a178d88cd1ba39057912292dfe714e1	ae5e865b009c2c8d10b683e7907104247c10ca41cedfe74f395bb397f582c58f
RUTX_R_00.07.07.2	02f69a5ca1254bc4838f7e34cd8d810	5f6aaf7c5b196f84d26e6040e3052998b83fe97b1abcaa5b4709f72e97caaa4b
RUTX_R_00.07.07.1	8e428314520a8afc6206aad40a81cd63	284e15f2a5bfd71e6c5c6388e97db16fbaf7fac0aa4a2cfc3280ce7f7eb36728
RUTX_R_00.07.06.10	6ade4748118720d9f8c72524498acf69	7e9a82723e384b5f8f385a2acda2ef3bb031b979840741e9b6e8c879398dda5a
RUTX_R_00.07.06.8	82faca5855d0229a1173f5a8409a248a	38d5bf4bb1592828c610773aa9c1619e0ce7d316532e0a48f1348e9def0502
RUTX_R_00.07.06.6	83c01f410d4c3060dd25f17128e4e000	827c78cdb5df433c7f19d76f7d2936693d0e20d8763077958e9dc8a21d5a3bfc
RUTX_R_00.07.06.5	164db26a0e142e7c4ce5c8cf55b4b8ee	66c133cddb07f62fc3d45fd5aea8984dd157efbe09eb063e3a659ccb6e1562a8
RUTX_R_00.07.06.3	66cf34dfd6ddf15187d9960bb2080f1	149c63d1130aeedd19b58cb43cf7ee050db4b16985cc170c57e85dd8c19366d8
RUTX_R_00.07.06.1	9281560d4a2bbf9f0166c9420a2ae496	03641567f495198f640ce69f0d457bb81a090c2d6e5d50ad86908bf581b85f8d
RUTX_R_00.07.06	e61775b7405f72b43b1ed36cfdcfcd26	14c66353e600f0e0256b0ee9cc2ed57f5db9c31bfff5f524c08b4913e5a3bc1537
RUTX_R_00.07.05.4	cef6d2843aeb024c25b85e2825114936	8eacd4815d95406136f120bd1db0642475899e9341be3ddf0858a1f395b5ea10
RUTX_R_00.07.05.3	8dca4917af4599b8e311ac576213c658	ad67f42efc9a972bc9f60a54880d761e5b4a655aa463b55402a4b635aedbfd52
RUTX_R_00.07.05	4037aa4f62af6d5fa99ecb2656f583f9	08e04dff1f4d3ab2e3018a1d88aff17125ec4cf5ccf3b813137a9d3a504fb4af
RUTX_R_00.07.04.5	62a4964e9a74eed6f068d1142824361f	1be7f7bf60bf2a1223f2fa0057b9196949415db4fc7ab2904e0250b40d1da9d1
RUTX_R_00.07.04.4	e5340026dbc6c61a182808ab64c5cdf9	dc0b77db5e611d8393ba37d3299c98c15227bb4cd17392d20414ef4e0dfd5700
RUTX_R_00.07.04.3	6fa297b7c444ad954685f44a8604ead4	76c18398adc601c74ff001a3697ead2c20058ddc09325b983104b95c9f475abf
RUTX_R_00.07.04.2	c43b3d1548a95d2ba832fa47228e7c8a	54882bef53ef18b0cb5bb5e4baecca62cd980100dac93d7064241d130108dc86
RUTX_R_00.07.04.1	967b54b584b35cd6eaba44d5cc6022f6	e0803aa221d9683756d092a9297aea00834f6aa470cb64158277503b976dcf6b
RUTX_R_00.07.04	9d69f40cd820d5a60180a8a6495a3316	6f6623c9177ca6993559a9b2b41cf74ee246b9aa9a7afc7e0a878745f2f78993
RUTX_R_00.07.03.4	29a2ac82a6d7336ef79cdd431871a1c4	75ba847509751883a22c8c257ecaec79e5c4fa4902a72849bf9fc177f3a0691f
RUTX_R_00.07.03.3	09a8fa8c51581a007111f2dfefba0b47	0639017f3912717381fd5265945ffbf8e83335f45554696b30675008f4234734
RUTX_R_00.07.03.2	aba97565e21f1e7fbaacca021f9d7c3f6	917ff372cacfa9d0c61a67b13ded8f7a896405b45eac75b546be65d46988fab3
RUTX_R_00.07.03.1	f6219206eb171dc7a88759aa7fa13141	1cad7ae3263a32dbdaf4fd7a8b9e02d6b25a607cbeaccf7d04337c36029eabdc
RUTX_R_00.07.03	f6550c87d4085b1f103856b35e6bb33d	512b261a88008af80f58bca3ec0271070f87c7935f3c242e538c0a89725850e9
RUTX_R_00.07.02.8	13aeff8ef12932814838bd504d47e2cd	b4e2f1804a318381794b7c8b8ec8c5c2bda331d0590249510bf17e52be797ae
RUTX_R_00.07.02.7	aea897b9a7f49b2fc0d8e237873a6247	d3326dc8a59a0fbf9860cf50f83925849f5587e04bdf3a794968d7bc992e60d7
RUTX_R_00.07.02.5	e23c03ab69a9510c59cf9a3ac22e149	1fd66ac57351a71ef55a5257270fe543bf8ea23b01686ecae7cee11b5c4fa9ebb
RUTX_R_00.07.02.5	589f2f3a344743c1cd438815096af1bb	1f9e40137f1142fb49f20b2404284d09ceef2e0611d49a012d66e9e5f7879a
RUTX_R_00.07.02.4	c91fc9cf9e9c0f91f067370f7a369b54	bcc49bdd1dd04340ed22e54805669764a8f907a808c37702859cda6d78d04ae
RUTX_R_00.07.02.2	c01711f3fa5a7679d736bc2777153cd0	e0c8ef995f7110534038ae95a101e27d6ebff63968d26ba3f7083cb4120872da
RUTX_R_00.07.02.1	bb9b9d052f147f2d98b17e8ead273933	5b9f6f737a652f912fa379e83cb0be6ce16691a9d38db9c8e9e17038d5918c24
RUTX_R_00.07.02	c8b63e143a28a2b633039c007fc379c5	193ae47a5849ad7c05b658bf32c929bde21bd3f3395bd36eb243dea3e54ce83c
RUTX_R_00.07.01.4	b38a975adf42d1c25f1ad6467d893434	094163a2bab17728aa8aad40570d1fc63e1d0558fb559e44dd665552a831621d
RUTX_R_00.07.01.2	180dfc0557bf9e7d53e3fcd9c33616a1	d3c6498a56428593f18cbf3e430ebbb149406b8dd22199bd92996f8ee5f7879a
RUTX_R_00.07.01	6b1991a1bed2713d01fdff681a7490245	3cecc4093b24cc0efb87ce463af72d5b38d0b5406e0950e9475627e19286a492
RUTX_R_00.07.00	57aef24b60a5718ca2d9657d05249c71	68cf3cea941abe44b190ed42770e31406b92dbcb85421fa5da0151b8d2bb2d08
RUTX_R_00.02.06.1	e3da056d210be7cef5dc57567259bc6d	b84d98992657c99dc330bfedf654e4bdd5b372949b2aa30530a6a1f6faa3c32
RUTX_R_00.02.06	11941c400f049f2a925c4491bbd19c68	5977afc287be05324c56fd1186d0e8f327861d0f042ff6fce610eacc8dcf5638
RUTX_R_00.02.05.2	a5a26d79a4428c5b5634dbc0099d447a	9cc31515f07aab39fd240306ebe2828031a86e725682bf5ca3c2eb1dc06f18d8
RUTX_R_00.02.05.1	c45f78819cca91f9c3d44fc25a39f327	3a88454d4056f69b3e45a6fcd8d00464552cf838a2a25578c4da85a182a8a539
RUTX_R_00.02.04.3	c9118cd432d5fddeaaa52b544ac099af	8c841ef40710492581175c1e4f9ed2639f6894a5d014237123a90e50f37a468b
RUTX_R_00.02.04.1	1639050586d6873d248c1c7d31ec66a0	9ebfa4d2fa21b592634f4ca4b4a850c46c3f65da93dd3c3b6df7eee5acd0ff0b
RUTX_R_00.02.03.4	6f3444333dd2dacdd8cb47f577f97bb	6862efdb0535e1a150b63bee9f807a447ff89c3814ffe444208ca4c1f940a005
RUTX_R_00.02.03.1	2186e6b823d68f3037d8cd17f4220ad8	537969eef0917e6157c7876f7428c67c587fab89ff2a7c66c52cc9d5c872fcf
RUTX_R_00.02.01.1	1ee3e5c3eeba30f0de516bc69d237b8d	7d02014d67655113368b73db849b568bcd539fd69ef9e5c9dad0a1d756a8af
RUTX_R_00.02.00.2	e8cc6da35ad7b8c24b70e08aa1dba425	4181daa4c25fa137c71e9d83add679790f039f7b34b1ad3d4212607390e4811f
RUTX_R_00.02.00.1	5b9433e22fd1b5647890d98238ae8381	1598ebda597410b444ae61450222c4bf56899c0349d1fb16349872e112e5d44d
RUTX_R_00.02.00	eee8bc405f9e50b3fd6a25e7a8cfb6	be104038a8ae698d5d1204699a805fcd499f0201fe90540bdc7b23b937797dd9
RUTX_R_00.01.06	086c7ea926d76c1e830aa3a6f01dae68	a1d989cb6504bf5712b7846817f832805845b669f75aece084f931365bc9f3a
RUTX_R_00.01.04.5	30c4653207425a4836590c3cfac66dfa	4f971276ea903a5017ed48f566f97116d15fd8446f6a5394a93df505b3889036
RUTX_R_00.01.04.1	f970ebf501444f387d6be5bb8d868345	e889521e510b104e6dac755dcc57987fbbcb20e984cb95834ae3baab35117c
RUTX_R_00.01.03	f77b59f377ee5a166733b4b3a95a1f2e	402fe342fe1e098007072afafbf11e0372813f22a35925238a11df201156260
RUTX_R_00.01.02	3c29f6d0cf00da48808f8abf035150b1	c54d26afd083e4b5e07c4d282715f3e6ff7c54b4552d24e217203fe63300653c
RUTX_R_00.01.01	3cbb32335b60c36aed7cd1dfef983a45	5b9b414977995a3a9f5b12ae2451da09434e248af3be52919ffa12ec2e8f87dc