

Template:Networking device firmware checksum list TCR1

FW version	MD5 checksum	SHA256 checksum
TCR1_R_00.07.08.2	9a31bc6ab15298860450083f3747f19f	af909b861e2ce727abddfa717ad214066667dd299d89175fea88d617d72d9d87
TCR1_R_00.07.08.1	da593570437b960dff7bf2dabb1062	cf0f6daa2f0db8263b01199ab0e9fac9218f84c5c557c3a908a40c13753bedd8
TCR1_R_00.07.08	d166a4d18f5e9a0fe3aaf20c865b8421	701deda738c641149dff9e5b93248845b3585b3bdf389649b43a13e55e0e53
TCR1_R_00.07.07.3	9a06ab2b888d07c9665790f7738ab887	83fe12bcdec703ac32e828395fa778a43096ef0345461a882330fa2cf069f614
TCR1_R_00.07.07.2	f6e41fc3cc86908e7b305de5b5f078db	60bfdad57b28c2c3015f8804910dc6052eb261f70c90415b3bc02909ec64b3f1f
TCR1_R_00.07.07.1	566fb715fe27ad0cdf8d00ecd4de2508	18ca991f62365de2908016e7b142b76dfa6c6171fdd9ef2b072466da143b5c24
TCR1_R_00.07.06.3	a7ca517bab654d090e2e02aa21bfd9b8	1b7a88a264a99a6b9afd01e0a99cdfd1b0858c2357cf5c29b58dcfa231362a11
TCR1_R_00.07.05.4	ab475a5d3564755c1d4207a8cd7ae8a3	53904d6233df5440a5eb250ac994c6e67c18c556c59a54547a6b786adf7c0b57
TCR1_R_00.07.05	270165f598baf8c5b7f33daede7280e5	b1cd0915833c267cae738c3054abbe7f0350a57298a4e9bd6331f7bebd29170f
TCR1_R_00.07.04.5	5030dce42b750027af23563ab22fbcbe	44142354a69f8191d269c12a0941b6145271fd93c77bbd448fcb120b95b2e939
TCR1_R_00.07.04.4	43844b2b36a0e71f1cc04a9b054722fa	b86846700e118bdfae30c4d0a2d80a0a3df7ef58689b4b50ef9df6c0f65e904
TCR1_R_00.07.04.3	e9b7b60eedd8a62b1c31a9c9f1c23bed	8d1aa7071fe27be2ee3e27ba287ffa74560ae310e4e5b8d2b1363cae32091099
TCR1_R_00.07.04.2	5e0338320b619a77107a0c185ad8d779	c1e2a64a8df0045d99bb6defe1ca519e05918d419266ed2703cf082f5a6c80b4
TCR1_R_00.07.04.1	82c2c5a3ca41fc015812194a20683b41	3c1c71c59f761f2e812e26ca7130480dbed6680cd2a1935877559a9f5499f683
TCR1_R_00.07.04	8a3589b79f6593ed6f3216db799102ad	a94d99c4d00e38ba3de2566363cb92b72a60d26ffe809dbd5a85e7cb43e997b1
TCR1_R_00.07.03.4	4239220d2319704d2fa01395adfcdb72	a58f93dfdcf06512d48e949b11441e28adff32b5430da3e60e0c4eed98dec809
TCR1_R_00.07.03.3	f71ab0d3230d16a2068e9a4fd2bf71e6	0e76ad5cbb6acc93be2b54afa84b6a049c47eddeb3fe4d58cb88daf81a871623
TCR1_R_00.07.03.2	6aef5ebff6fa7a7af4372eeb7ad7700	85e02b2c8bcbbee0851bf92bbdabb3c6b7f6a17c1a3f5a08d3649606659837dc
TCR1_R_00.07.03.1	7b0f6c14da44ba979027bcc28d09f3eb	2b0493626140a2f28fb725724604adb5c0ac7287b56d6396c831caaebe21871e
TCR1_R_00.07.03	0f89931b7a848a8d10e6bda33fd217c1	a8e67ae5c22a64cab11ec02f59d06cb32f58d97d1d87e7cdc8f93a095d23b9e1
TCR1_R_00.07.02.7	001b9e6cf7b1ff928ebe3364d3b5ef41	41c829c01ed86cdbc6e093f2aea9b2ebad30488623b63e0748764586bd2bebf2
TCR1_R_00.07.02.6	f9fe4ea7aec029b9b93444d5bf2b0842	221b1ae3cdd7d577f558cf1e709cbf7b3c91d5e61bcdd694e652ec188d26a25b
TCR1_R_00.07.02.5	91443e1ca665640aba0821646aad3dd3	f075ffdda742dc78037eeec34081e11ab5f2916564bba69ee14c6603900dce23
TCR1_R_00.07.02.4	31874b5268dbf093369cb0201e36db63	807b3cec82c8ad92a0227b7d5c4d9fadce375cd61cdd80fa1dd78b553df22528
TCR1_R_00.07.02.2	b96fe09e07217a04e6c4283e7ed41581	3ea4e87ceda88c49b131e02ca8313b86db632525dba8567ef97b65018ddd90c
TCR1_R_00.07.02.1	180bb71996c941f67f575093e29403f	bbe8f963ab737b8e0ea6a8612a8c42fd9cba8246c6c6d27cd2737b7c823ca281
TCR1_R_00.07.02	87d378ab20e3a4c65bdcd9d5e04fbc8a	3460df35d2917c91a329c790ab495a702c1f2e73697ee506a3731d182f2d4556
TCR1_R_00.07.01.4	71cb92854324e54eea6909709c366e3	da63de1575ee80d0ecbc424326b87c121ef835bc6e63e935d0337233c5d44cfe
TCR1_R_00.07.01.2	56a76744480ea45618d3dbe52333f1a0	4abbc83414a1521560adb6ef049a3ba444d1653c1914aa386c1f7cf7ce981e3c
TCR1_R_00.07.01	7123be214b8292326f838e8b802b60b7	a2399b3be13ac65f72ad4ac326cce2f75aa25a4854d3270709aadbf08bad302c