

# RUT956 Product Change Notifications

[Main Page](#) > [RUT Routers](#) > [RUT956](#) > **RUT956 Product Change Notifications**

**Product change notifications (PCN)** is a way of informing customers of upcoming changes related to Teltonika Networks products. This includes outward appearance adjustments, hardware improvements, changes to package contents, etc. Changes related to a product's firmware are not included in PCNs ([click here](#) to see the firmware changelog).

This page stores information regarding changes to the [RUT956](#) device. Below you will find a list of both upcoming and already implemented changes sorted by newest to oldest (top to bottom).



## Contents

- [1 2024.03.08: Reset button functionality change RutOS 7.07](#)
- [2 2024.01.10: New PCB revision](#)
- [3 2023.09.04: Packaging box changes](#)
- [4 2023.06.07: QSG flyer replacement](#)
- [5 2023.04.17: Product packaging changes](#)
- [6 2023.02.13: MAC address range change](#)
- [7 2022.08.18: Default password change](#)
- [8 2022.08.18: QSG flyer replacement](#)
- [9 2022.08.18: Changes in engraving/labeling](#)

## 2024.03.08: Reset button functionality change RutOS 7.07

With the release of RutOS version 7.07, RUT956 device will experience changes related to the security improvements of the device.

PCN Number: PCN_RUTOS_CHANGE_2024_03_08_EN		
Change description		
Change type	Firmware change	
Detailed description	Previously, during device resets, logs, RMS connection state data, and SIM PIN settings remained unchanged. However, starting with RutOS firmware version 7.07, all devices will uniformly reset logs, RMS connection state data, and SIM PIN settings to factory defaults when using the reset button. Other reset methods, including WebUI, SMS, and others, will remain unimpacted by this change.	
Change reasons	Increasing security	
Affected products information		
Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2024 Q2, with the release of RutOS 7.07	
Change impact		
Risk assessment	<ul style="list-style-type: none"><li>• The loss of device logs upon utilizing the reset button may disrupt operational records and slow down subsequent troubleshooting efforts.</li><li>• Failure to set up the SIM PIN post-reset via the reset button may result in SIM card lockout due to repeated incorrect PIN entries, causing service disruption and requiring either SIM replacement or PIN reset.</li><li>• The device is still visible in RMS post-reset but cannot be accessed. Therefore, re-adding the device to RMS is necessary for continued access.</li></ul>	
Suggested implementation plan	Information included in this PCN will help adapt to the upcoming changes. For more detailed information, please contact your sales representative.	
Acknowledgement of PCN receipt		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		

To download the pdf version of this notification, [click here](#).

## 2024.01.10: New PCB revision





Starting from Q2 2024, RUT956 routers will be manufactured with updated MAIN and RF PCB revisions.

Change description		
Change type	Hardware change	
Detailed description	Starting from Q2 2024, RUT956 routers will be manufactured with updated MAIN and RF PCB revisions. The following are the detailed updates made to the MAIN and RF boards:	
	<ul style="list-style-type: none"><li>• Added micro SD card support</li><li>• Added new USB HUB</li><li>• Added new USB-UART ICs</li><li>• Added new ADC</li><li>• Added SIM card presence triggers to SoC GPIO</li><li>• Added shift register clearing circuitry</li><li>• Added pull-down resistors on pins to address potential issues that may arise when shift registers are in the tri-state high-z state.</li></ul> Please note that this change will be implemented gradually, throughout a 3-month transitional period starting from Q2, 2024. During this period, your shipments of RUT956 may consist of either the current packaging or the new one described above.	
Change reasons	Hardware design improvements	
Affected products information		
Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	Q2 2024	
Change impact		
Risk assessment	New hardware support starts from RUT9M_R 00.07.06 FW version, older FW versions will not be compatible. Custom firmwares created from an SDK will need adjustments for a new SDK version.	
Suggested implementation plan	Firmware downloads for the device can be found <a href="#">here</a> . For more detailed information please contact your sales representative.	
Acknowledgement of PCN receipt		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		

To download the pdf version of this notification, [click here](#).

## 2023.09.04: Packaging box changes

Starting from Q4 2023, batch 017, the product packaging of RUT956 will be updated with the following changes.



Change description		
Change type	Packaging	
Detailed description	The fibre inserts of each product and its accessories will be replaced with individual cardboard boxes. Of those boxes, the product box will include the Teltonika Networks logo and company information, and accessory boxes will include the accessory name, order code, image, EAN barcode, and QR code. Any empty space in the packaging will be filled with Corrugated fibreboard fillers. These updates are meant to reduce the environmental footprint of our products, with eliminating plastic packaging being the primary focus. Please note that this change will be implemented gradually, throughout a 4-month transitional period starting from Q4 2023, batch 017. During this period, your shipments of RUT956 may consist of either the current packaging or the new one described above. For inquiries regarding custom order codes, please contact your designated sales representative.	
	<b>Current packaging:</b>	<b>Updated packaging:</b>
Change reasons	 <b>Device box:</b>	 <b>Corrugated carton filler:</b>
	 Packaging dimensions will not change.	
Design improvement.		
Affected products information		
Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2023 Q4	
Change impact		
Risk assessment	The product handling and storage process may require review. Marketing materials, such as photos, might need replacement.	
Suggested implementation plan	Information included in this PCN will help adapt to the upcoming changes. For more detailed information please contact your sales representative.	
Acknowledgement of PCN receipt		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above		

To download the pdf version of this notification, [click here](#).

## 2023.06.07: QSG flyer replacement

Starting in Q3 of 2023, RUT956 routers will come with a new QSG flyer in the packaging.

### Change description

Change type	Replacement of QSG flyer	
Detailed description	RUT956 devices manufactured starting from Q3 2023 will have a new QSG flyer in the packaging. The new QSG flyer includes multiple languages, English, German, Spanish, French, Italian, the short version of QSG with a QR code/link to the full Web QSG version: <a href="https://teltonika-networks.com/QSG_RUT956">teltonika-networks.com/QSG_RUT956</a>	
	Previous design: 	New design: 
Change reasons	The new flyer will include QR codes with URL links to RMS and the Web version of the QSG (Quick Start Guide) for the RUT956. Introducing additional languages.	

### Affected products information

Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2023, Q3	

### Change impact

Risk assessment	Marketing material such as photos might need replacing.
Suggested implementation plan	Information included in this PCN will help adapt to the upcoming changes.

### Acknowledgement of PCN receipt



If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, [click here](#).

## 2023.04.17: Product packaging changes

Starting from 2023 Q2 RUT956 router product packaging will be changed.

### Change description

Change type	Packaging	
Detailed description	The packaging for the product will undergo several updates including an update to the side print of the box. Additionally, the box will now feature press with certificates that will be printed according to the region. Finally, there will also be changes made to the company information section including the address, telephone number, email and website link.	
	Current design: 	Updated packaging design: 
Change reasons	Packaging dimensions will not change. Design improvement.	

### Affected products information

Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2023 Q2	

### Change impact

Risk assessment	The product handling and storage process may require review. Marketing materials, such as photos, might need replacement.
Suggested implementation plan	Information included in this PCN will help adapt to the upcoming changes. For more detailed information please contact your sales representative.

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, [click here](#).

## 2023.02.13: MAC address range change

All Teltonika Networks devices manufactured starting from 2023, week 9 will have additional new MAC address range.

### Change description

Change type	MAC address range
-------------	-------------------

Detailed description	All Teltonika Networks devices manufactured starting from 2023, week 9 may have a MAC address from the new MAC address range <b>20:97:27:00:00:00 - 20:97:27:FF:FF:FF</b> , as well as the current MAC address range 00:1E:42:00:00:00 - 00:1E:42:FF:FF:FF	
Change reasons	Endpoint of the previous MAC address range.	
<b>Affected products information</b>		
Model	Affected order codes	Order code changes
All Teltonika Networks devices	All order codes	No changes
Upcoming change date	2023, week 9	
<b>Change impact</b>		
Risk assessment	Device install procedures or any automated solutions might need modifications.	
Suggested implementation plan	For more detailed information please contact your sales representative.	
<b>Acknowledgement of PCN receipt</b>		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		

To download the pdf version of this notification, [click here](#).

## 2022.08.18: Default password change



All RUT956 devices manufactured starting from 2022, week 35, will have unique default password.

<b>Change description</b>		
Change type	Default password change	
Detailed description	RUT956 devices manufactured starting from Q3 2022 will have unique default password.	
Change reasons	Increasing device security	
<b>Affected products information</b>		
Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2022, week 35	
<b>Change impact</b>		
Risk assessment	Device install procedures or any automated solutions might need modifications. <b>Please note:</b> this product change notification does not affect any previous RUT956 devices.	
Suggested implementation plan	For more detailed information please contact your sales representative.	
<b>Acknowledgement of PCN receipt</b>		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above		

To download the pdf version of this notification, [click here](#).

## 2022.08.18: QSG flyer replacement

Starting from 2022, week 35, RUT956 routers will come with a new QSG flyer in the packaging.

<b>Change description</b>		
Change type	Replacement of QSG flyer	
Detailed description	RUT956 devices manufactured starting from Q3 2022 will have a new QSG flyer in the packaging. The new QSG flyer includes the short version of QSG with a QR code/link to the full Web QSG version: <a href="https://teltonika-networks.com/QSG_RUT956">teltonika-networks.com/QSG_RUT956</a>	
	Previous design: 	New design: 
Change reasons	The new flyer will include QR codes with URL links to RMS and the Web version of the QSG (Quick Start Guide) for the RUT956.	
Reducing environmental impact.		
<b>Affected products information</b>		
Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2022, week 35	
<b>Change impact</b>		
Risk assessment	Marketing material such as photos might need replacing.	
Suggested implementation plan	Information included in this PCN will help adapt to the upcoming changes.	
<b>Acknowledgement of PCN receipt</b>		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above		

To download the pdf version of this notification, [click here](#).

# 2022.08.18: Changes in engraving/labeling

Starting from 2022, week 35, RUT956 routers will be produced with modified bottom engraving/labeling.

## Change description

Change type	External/visual
	The device's unique default password will be added to the bottom engraving/labeling. The formatting for the remaining information on the labeling/engraving will be adjusted, and the Fira font will be used instead of Arial. The device's unique default password information will also be added to the QR code Information displayed after scanning QR code with syntax: WIFI:T:WPA;S:{{WIFISSID}};P:{{PASSWORD}};SN:{{SERIAL}};I:{{IMEI}};M:{{MAC}};U:admin;PW:{{DEVICEPASSWORD}};B:{{BATCH}};
Detailed description	From the device top engraving/labeling, the previously relevant authentication information text will be removed: <b>User/Pass: admin/admin01</b> .  The labeling on the product packaging will stay unchanged. <div><div><b>Old top engraving/labeling:</b> ✖ <b>Old bottom engraving/labeling:</b> ✖</div><div><b>New top engraving/labeling:</b> ✖ <b>New bottom engraving/labeling:</b> ✖</div></div>
Change reasons	To accommodate the change from the standard default password to a unique default password for each device.

## Affected products information

Model	Affected order codes	Order code changes
RUT956	RUT956 *****	No changes
Upcoming change date	2022, week 35	

## Change impact

Risk assessment	Changes to top labeling/engraving. Device's unique default password will be present on the product itself. This might impact marketing materials due to changing contents of the bottom informational engraving/labeling.
Suggested implementation plan	No implementation plan needed

## Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, [click here](#).