

TRB2 Firmware checksum list



Contents

- [1 Summary](#)
- [2 Checksum list](#)

Summary

A **checksum** is a sequence of hexadecimal symbols generated after running an algorithm called a cryptographic hash function on a file. Calculating a checksum and comparing it with the one provided by the file source can be used as a file authenticity check method.

For example, if you download a file like a firmware image, you should be able to calculate that file's checksum and, if the file is authentic, the checksum should match the one provided by the file's source. If the checksums don't match, it means the file's contents were tampered with, for example, by a malicious third party attacker. This file is probably dangerous and shouldn't be trusted.

Checksum list

Firmware file checksums are listed by firmware release date, from newest to oldest (top to bottom).

FW version	MD5 checksum	SHA256 checksum
TRB2_R_00.07.06.10	6d4d3497e47eef0b33b7772c8c6d12df	33ac1e53ed3796106e4f303ba48eec9411b53e800debc2af84839073af0833f7
TRB2_R_00.07.06.8	07b8b99925578479643951132ad8e61f	aaa91f891f33b2f6c4a39a23e61d58c096957701a93cc410aa7bd19839b7ee3c
TRB2_R_00.07.06.6	49b32b97611ca61f6ff28151d7ebfa68	eb7f9c9bc91f9d7fa9cf399074e1c5c1efed7f36ff8b5ced5bf3c8752603e107
TRB2_R_00.07.06.5	34f686ec31e27e8b4b9ba558505aa99a	67c6d3941affdc3f2c06be089c733345da3a4693f7b4873dba269122cdb24c6b
TRB2_R_00.07.06.3	2bc6e9dcc300d61120421ea7892b1720	0d50da23636f47f8fd178b332af61c63327ebdce6a0ab8c32a81fc2373c4ac67
TRB2_R_00.07.06.1	b65fb753643c8214e8fd6efd7a41066c	98b79a822b785f6e98e427fe4cf21854cb3023122cc7d0bb5be3d9c7870f8b72
TRB2_R_00.07.06	04684957d6f6b1823cd2dd7e39a59ec4	e9b6139b0d3984e346cd7a1c7edd17a5be45fd01bb070ec253dbec99518cf9bf
TRB2_R_00.07.05.4	8c40f41802182c7391241508e2241e9c	3370e1dedecd9aefa18ae16709be6ae4c9216196bfe1947096c24493552b8881
TRB2_R_00.07.05	9b066bef60cec877ecec7b4c929b5bf	a6cd6da9c4518f936fafb672a39fa917a5b2803b0642315f3def30298353eb92
TRB2_R_00.07.04.5	713498c349114ce47de12c30fbc6d7ec	7a8a39a0c390fea71eea8e6cdb9fe63e53543e61c3b7105de46653748c34abb8
TRB2_R_00.07.04.4	a8ff5b3b9c430039f56401499b150f1d	adb6bc9fd66828303a738fe479806e8b5bf2c1d4a63c604989eabdc16d089e72
TRB2_R_00.07.04.3	6a59dc0d97472faa5f990dca88b7d353	3f2016bfc923a82c052b53e895403923373f9eb13f5f3c77473ae8349fc3be14
TRB2_R_00.07.04.2	6e64b5178561b73a6449239c2788adc0	b1b0c6999c93c7115a13ad850bd36ec89f375971f40a4370b3fc371c85903e2e
TRB2_R_00.07.04.1	362ae60daf7fecfec45df28a93c72349	665d1cf0006badafb39a08dce69385cc12362a4d3f5de1487d40f200c0f7e782
TRB2_R_00.07.04	b6b64ec8734126935750e5296ea8cbbf	be38bbbae58dec2f3462b4caf5887c6dff049daea33f9498983ddc2605ae76d1
TRB2_R_00.07.03.4	cf1b99ab30ddae6913b4da4876023df8	6e05b83bbd09d715ec75249447579ca92796f9f8c90c934fbc833e03a9ba858e
TRB2_R_00.07.03.2	c6b28be09b239a36c677ca9587c6f9b9	3c7abb9aa4018cc14e754157eea42a2ef4e67be7cb92ad02310e4e6b94fdf84b
TRB2_R_00.07.03.1	f0ab72f5e1629646a68c521dd4cec062	91708691d3dbfce9f368625f33ccb700fa992449e49a0999c5960cf79c589b5
TRB2_R_00.07.03	730395019e8a5f1e8f24b53ed417cfb0	12d2b2ede5577575892e84dd145dc1e477eca08ea760e3fcede9b394f101eb93
TRB2_R_00.07.02.7	b897be5d55d966599069252810e84038	c660d9785f70f6e1a9991ad5cc393484076b77ac25316dc79f8bae8b2d4cb60a
TRB2_R_00.07.02.6	7a8568fdc5e557fed8d0df898408bfb9	80edbd93896d2fc74e442b3203e896c138e5368822f04774cbf0bd06bdb541a
TRB2_R_00.07.02.5	81cd225671b598897edd9e8f5b149607	3e6e29e8a88514642200165ae96f7287c4c030379a758cca757a4a04b816e4a
TRB2_R_00.07.02.4	f20596181fe69597747a809bbd7db340	124e2749ad9c091100a495be9128a8aae03494ec51d76118eccc56dbc4d04ef5
TRB2_R_00.07.02.2	2baa1ac705d6adc96401bdcef7c80bd4	2601c36e75f79b2073fedc511f8b5758332a62a895767746d410adda2501be33
TRB2_R_00.07.02.1	f2e5beb3572b4a72b6130ef1bf447273	9001613d427fea4e55e7704e7bc4c982d3710c7b6d760e44a275fcbf850ab2b58
TRB2_R_00.07.02	e327b33531e7586156f02c2d8c54d77c	35e77e41bfd546e10e139b6492a62cbad1f0456975f270efe4574067c3724843
TRB2_R_00.07.01.4	2fb6275489bb04833dcf02bc2c996d10	dcae2f6f008aed92a37cbeb23f326ef47e6b5655c26a49deba95c025e3a7bba0
TRB2_R_00.07.01.2	734c77671933eded76ca6656aad37eca	b8044d734d7d4e715c50fd196de1cff28ddd4ea438f310030f1950ab09af98c8
TRB2_R_00.07.01	f1a6631c2fa37f2feeb55298654347a6	221050be1c7a28f191f35fa4c288ac0038f5e2035a3b599ced20b55fd7a58521
TRB2_R_00.07.00	e7cf046e9cc42347872956dcd8f6f996	046b819ba67508af13e405602b7aede3f1ab07e4514d65dff485a53e4ba661
TRB2_R_00.02.06.1	94a80b45777b155823029982cb31560e	549fbd524d1c238b6e10f407b3f3ecaabd9ca64c7c830898259299cedbfb5cf4
TRB2_R_00.02.06	dee686ddd4c4861f088121f98ff6d5bd	f46f1e4ac903ecb4f856c4155aea6675872697638df3e47b8ae5fceedb0caf5

TRB2_R_00.02.05.2	976377b1f46d9cbd37d6085f742ce868	3be65b9b2f4464b6e3c5dd5511fc8cbe7b50dc7496f66f5cd0e6612f21820ae8
TRB2_R_00.02.05.1	b724a417a13be1ee35555d434a96a3dc	15836da12b23c4857fc86ee6dbaeb7ca07755c22fc82b821a6e6f29451b8edfe
TRB2_R_00.02.04.3	799b6fe5be2d0954460261545b504beb	59bc1c009019ecc0ff2c3fd7f8170af157a755d1e310c36303eadd178eb2505a
TRB2_R_00.02.04.1	b6df6fd6f75f8b47c7c9e732cb17fd	1f8a802a0dcdcc3f6132506f77ee5f62348c1daec04c1d0b4702351e1ae9b051
TRB2_R_00.02.03.1	8fd9ffef61007b0d79618399df21fc5d	dc79ad679713cc165910ac964f85c20966fadbe295124d5179926377144ab0b2
TRB2_R_00.02.02	3f3ea1fcceafea231a8fffdcf11e5065	c92270c2823fb98cc34060f68737ce1675f86269e541d0e52012bbcd571dd2bb