

2025.07.22: New RUTX12 hardware revision

Starting from Q3 2025, RUTX12 routers will be manufactured with updated hardware and will require firmware version RUTX_R_00.07.16 or newer to function properly.

PCN Number: PCN_RUTX12_New_HW_revision_2025_07_22

Change description	
Change type	Hardware change
Detailed description	All RUTX12 devices manufactured starting from Q3 2025 will feature a new hardware revision. Devices with the new hardware will require firmware version RUTX_R_00.07.16 or newer. It is recommended to use the <u>latest firmware version</u>, at least RUTX_R_00.07.16. Starting from Q3 2025, RUTX12 devices will include the following hardware changes: ■ Added possibility to manufacture with eSIM ■ Manufactured with TPM ■ Manufactured with an updated Bluetooth chip Please note that this change will be implemented gradually, throughout a 3-month transitional period starting from Q3 2025. During this period, your shipments of RUTX12 may consist of either the current or the new hardware as described above.
Change reasons	Hardware design improvements

Affected products information		
Model	Affected order codes	Order code changes
RUTX12	All	No changes
Upcoming change date	Q3 2025	

Change impact	
Risk assessment	All risks are firmware-related. It is strongly advised to test firmware release RUTX_R_00.07.16 or newer on the updated RUTX12 hardware revision devices. New hardware support starts from RUTX_R_00.07.16 FW version, older FW versions will not be compatible. Custom firmwares created from an SDK will need adjustments for a new SDK version.
Suggested implementation plan	Firmware downloads for the device can be found <u>here</u> . For more detailed information please contact your sales representative.

Registration code 305579419
VAT number LT100013223510

Swedbank AB
LT78 7300 0101 6274 0111
S.W.I.F.T. HABALT22

www.teltonika-networks.com



Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification, Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.