

## 2025.02.25: Mobile and I/O POST/GET Service Removal with RutOS 7.14

With the release of RutOS version 7.14, support for the RUT241 POST/GET service will be discontinued to enhance security while maintaining device functionality through alternative methods.

PCN Number: PCN\_RUTOS 7.14\_POST\_GET\_Removal\_RUT241\_2025\_02\_25\_EN

### Change description

|                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Change type          | Firmware change                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| Detailed description | With the introduction of RutOS 7.14, the Mobile POST/GET and I/O POST/GET services will be removed from the firmware and will no longer be available in the package manager. These legacy services had security concerns, and their removal ensures a more robust security framework for the device. However, users will still be able to achieve the same functionalities using the device's API, which provides a more secure and efficient way to interact with the system. |
| Change reasons       | <ul style="list-style-type: none"><li>Enhanced Security: Removing these services mitigates potential security risks and improves overall system integrity.</li><li>Improved API Support: Users can leverage the API for secure and flexible data handling without relying on deprecated methods.</li><li>The change aligns with modern security protocols and best practices in remote device management.</li></ul>                                                            |

### Affected products information

|                      |                                         |                    |
|----------------------|-----------------------------------------|--------------------|
| Model                | Affected order codes                    | Order code changes |
| RUT241               | RUT241 *****                            | No changes         |
| Upcoming change date | 2025 Q2, with the release of RutOS 7.14 |                    |

### Change impact

|                               |                                                                                                                                                                                                                                                                                                                                                                                                                                |
|-------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Risk assessment               | <ul style="list-style-type: none"><li>Clients using Mobile POST/GET and I/O POST/GET services will need to transition to API-based methods.</li><li>Some automation processes relying on these legacy services may require reconfiguration</li><li>API documentation and support resources will be available to facilitate a smooth transition.</li></ul>                                                                      |
| Suggested implementation plan | <ul style="list-style-type: none"><li>Test API-based interactions before the transition to ensure compatibility.</li><li>Review the API documentation: <a href="https://developers.teltonika-networks.com/">https://developers.teltonika-networks.com/</a></li></ul> <p>Information included in this PCN will help adapt to the upcoming changes. For more detailed information, please contact your sales representative.</p> |

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.

Registration code 305579419  
VAT number LT100013223510

Swedbank AB  
LT78 7300 0101 6274 0111  
S.W.I.F.T. HABALT22

[www.teltonika-networks.com](https://www.teltonika-networks.com)



Data on the company is collected and stored in the Register of Legal Entities of the Republic of Lithuania.