

## **Product Change Notification**

Change description	
Change type	Default password change.
Detailed description	TRB142 devices manufactured starting from Q4 2022 will have unique default password.
Change reasons	Increasing device security.

Affected products information		
All TRB142 ***** product codes are affected. No product code changes.		
Upcoming change date	2022, week 50	

Change impact	
Risk Assessment	Device install procedures or any automated solutions might need modifications.  Please note: this product change notification does not affect any previous TRB142 devices.
Suggested action taken	For more detailed information please contact your sales representative.

## **Acknowledgement of PCN Receipt**

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.

