

2025.08.19: New Hardware Version

RUTC50 devices manufactured starting from Q4 2025 will include a new hardware version and will require firmware version **RUTC_R_00.07.14** or newer to function properly.

PCN Number: PCN_New_Hardware_Version_RUTC50_2025_08_19_EN

Change description	
Change type	Hardware
Detailed description	<p>Starting from Q4 2025, RUTC50 devices will be manufactured with a new hardware version, identified by product code RUTC50 *1****. The new hardware requires firmware version RUTC_R_00.07.14 or newer to ensure full functionality and compatibility. Previous firmware versions are not supported with the new hardware.</p> <p>Key Hardware Changes:</p> <ul style="list-style-type: none"> ■ eSIM module installed by default ■ RAM increased from 512MB DDR3 to 1GB, DDR4 ■ Storage expanded from 512 MB NAND to 8 GB eMMC <p>Transition Period: The current RUTC50 hardware version (existing product codes) will remain available and can be ordered until 2025-12, tentatively. From Q4 2025 until 2025-12, both hardware versions will be manufactured and available for ordering. After 2025-12, only the new hardware version (RUTC50 *1****) will be manufactured and shipped.</p>
Change reasons	Improved hardware version

Affected products information		
Model	Affected order codes	Order code changes
RUTC50	RUTC50 *1****	RUTC50 *1****
Upcoming change date	2025-12	

Registration code 305579419
VAT number LT100013223510

Swedbank AB
LT78 7300 0101 6274 0111
S.W.I.F.T. HABALT22

www.teltonika-networks.com



Data on the company is collected and stored in the Register of Legal Entities of the Republic of Lithuania.

Change impact	
Risk assessment	<ul style="list-style-type: none"> All risks are firmware-related. It is strongly advised to test firmware release RUTC_R_00.07.14 or newer on the updated RUTC50 hardware version devices. <p>Please note: This product change notification does not affect previously manufactured RUTC50 devices.</p> <ul style="list-style-type: none"> New order code (RUTC50 *1****) have been created for the new hardware version, please review them here
Suggested implementation plan	Firmware downloads for the device can be found here . For further information, please contact your sales representative.

Acknowledgement of PCN receipt
If no feedback is received within two weeks after the issue date of this notification – Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.

Registration code 305579419
VAT number LT100013223510

Swedbank AB
LT78 7300 0101 6274 0111
S.W.I.F.T. HABALT22

www.teltonika-networks.com

