

RUTM11 Firmware Downloads

[Main Page](#) > [RUTM Routers](#) > [RUTM11](#) > **RUTM11 Firmware Downloads**

This page contains firmware files for RUTM11 devices. Look to the table below or the [changelog](#) to find download links.

To upgrade firmware using WebUI, follow the instructions in [RUTM11 Firmware](#).

RUTM11

File	Type	Release date	Size	MD5	Changelog
RUTM_R_00.07.07.3_WEBUI.bin	Latest FW	2024.06.25	21.5 MB	455d11885ab5ee5e898979e75ed493f8	Link
RUTM_R_00.07.07.3_WEBUI.bin	Mass production FW	2024.06.25	21.5 MB	455d11885ab5ee5e898979e75ed493f8	Link
RUTM_R_GPL_00.07.07.3.tar.gz	SDK	2024.06.25	40.1 MB	d94c241994084527c4bf42c61471aec7	

Note: packages for [Package Manager](#) are independent from firmware and can be downloaded in the [Package Downloads](#) page.

RUTM11 device firmware cannot be downgraded below [RUTM_R_00.07.06.1](#) version.

FW checksums

Checksums for firmware files can be found [here](#).

Changelog

[RUTM_R_00.07.07.3](#) | 2024.06.25

- **Fix**
 - **Network**
 - WebUI: fixed port advertisement change
 - **System**
 - FOTA: fixed config when upgrading from older firmware with keep settings
- **CVE Patches**
 - CVE-2024-31950
 - CVE-2024-31951

[RUTM_R_00.07.07.2](#) | 2024.06.12

- **Improvements**
 - **Network**
 - Zerotier: added backup WAN interface blacklisting if WAN failover is enabled
 - Mobile: improved communication stability with eSIM
 - **Services**

- SNMP: added bruteforce attack prevention when using SNMP v3 user
 - L2TP: improved reconnect attempt logic
 - Wireless: removed unnecessary information from system logs
 - **System**
 - SSH: removed weak SSH algorithms
 - Telnet: moved to Package Manager
 - **Fix**
 - **Network**
 - BGP: fixed instance migration issues
 - Mobile: fixed a SIM detection issue
 - Mobile: fixed forced APN configuration
 - **Services**
 - DMVPN: fixed duplicate NHRP map entries creation
 - OpenVPN: added fixes for the insecure tls-cert-profile option usage
 - **System**
 - IP Block: fixed blocking of UDP traffic
 - Ledman: fixed WiFi LED indication when WiFi configuration is changed
 - **CVE Patches**
 - CVE-2024-31948
-

[RUTM_R_00.07.07.1](#) | 2024.05.28

- **New**
 - Initial firmware release