

# Template:Networking device firmware checksum list OTD140

FW version	MD5 checksum	SHA256 checksum
<b>OTD140_R_00.07.08</b>	<b>90719e8380743b0ee7f5ce0c02fbecae</b>	<b>6d1c17d821ca50f48f9410e93e11072b23ccb07bba5ce38afd8f0e832e382cc0</b>
OTD140_R_00.07.07.3	c50ae2c13b4a54ffdc1975977790a19b	c9fd7765becd364325d23de8c4f0ec8f087899dc59b9b7f96300b5f7d5e19fd5
OTD140_R_00.07.07.2	1a6537bf7fdbfeeb365f05f63805a09b	19a51440e97f89341e792fc95a8254c3bdb2c8a871099f37f32ae43b2b16ec52
OTD140_R_00.07.07.1	ff33870e309f12391da0bd2947a75cfc	a76f0df531a2acb9b14f9cadd6930518d0e661b3059aa472e7a511ff5885626a
OTD140_R_00.07.06.10	6241a1a74588bdaa5ea1244e78f4739a	ca3ff188e756c27f9d7e37b8846da624b4c63885c942203dc701ea77d9d5c3c5
OTD140_R_00.07.06.8	75efda5ee4fb41b844ea52200d8b0433	3e0cf7f21e4eb86ff6f8fa97bd0627e2643089bafa7d7730187264df14ec761fd
OTD140_R_00.07.06.6	df2e68f32a72e96ed858a81f35f71e1b	80c45c35d12f36adc79a5b563230b336a5351be796f60156d121cf1745eb36cc
OTD140_R_00.07.06.5	22597594334ada4b36fe18b68ea61d0a	71637513dc67a184e60d66d488b003e1eba977755990b7aacff97fd4d06f9c0f
OTD140_R_00.07.06.3	dc0408f0e600fd41bd52589e0291ad2b	e94d3213ba2a2e6d6668f7250191379465d1298591a77f89a1a2f19c2a226061
OTD140_R_00.07.06.1	c2df49bb8365e06177cfd39a5c21e24	e014c3ae34c3289e8ed3d5008af397cffe7f22ac8eaea292126eb50da083c4b2