

TRB256 Firmware Downloads

[Main Page](#) > [TRB Gateways](#) > [TRB256](#) > **TRB256 Firmware Downloads**

This page contains firmware files for TRB256 devices. Look to the table below or the [changelog](#) to find download links.

To upgrade firmware using WebUI, follow the instructions in [TRB256 Firmware](#).

TRB256

File	Type	Release date	Size	MD5	Changelog
TRB2M_R_00.07.06.10_WEBUI.bin	Latest FW	2024.04.04	10.19 MB	0402549e8e317201f6f877dd3681ad51	Link
TRB2M_R_00.07.06.10_WEBUI.bin	Mass production FW	2024.04.04	10.19 MB	0402549e8e317201f6f877dd3681ad51	Link
TRB2M_R_GPL_00.07.06.10.tar.gz	SDK	2024.04.04	20.84 MB	36d4b9f932163ad3b11f7eba93d0bb5d	

Note: packages for [Package Manager](#) are independent from firmware and can be downloaded in the [Package Downloads](#) page.

FW checksums

Checksums for firmware files can be found [here](#).

Changelog

Global RUTOS changelog can be found here: [LINK](#)

* This is universal changelog of RUTOS. Changes made to features that are not present in some devices, do not affect them.

[TRB2M_R_00.07.06.10](#) | 2024.04.04

- Global changelog for **R_00.07.06.10** - [LINK](#)

[TRB2M_R_00.07.06.8](#) | 2024.03.25

- Firmware **R_00.07.06.8** was removed due to an issue with inefficient memory allocation for LED control.

[TRB2M_R_00.07.06.6](#) | 2024.03.04

- Global changelog for **R_00.07.06.6** - [LINK](#)

[TRB2M_R_00.07.06.5](#) | 2024.02.21

- Global changelog for **R_00.07.06.5** - [LINK](#)

[TRB2M_R_00.07.06.3](#) | 2024.01.17

- **New**
 - Initial firmware release