

Product Change Notification

PCN number: PCN_RUT2xx_20190619_EN		Date: 2019.06.19
1. Change description:		
Change type	Device Flash memory changed	
Detailed description	RUT2** series Flash memory changes. Old firmware versions will not support new flash memory, meaning that only RUT2XX_R_00.01.07 and newer firmwares will work with updated hardware. Custom firmwares built on previous SDK versions will also no work.	
Change reasons	Reducing product lead times.	
2. Affected products information:		
All RUT2** ***** product codes are affected. No product code changes.		
Product release date:	RUT230: week 33, 2019 RUT240: week 29, 2019	
3. Change impact		
Risk Assessment	All risks are firmware related. Custom SDK firmware an be re-built using these instructions: https://wiki.teltonika.lt/view/SDK: new flash support instructions	
Suggested Implementation Plan	Device firmware downloads can be found at http://wiki.teltonika.lt For more detailed information please contact your sales representative.	
4. Acknowledgement of PCN Receipt		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		