

## Product Change Notification

PCN number: PCN_TRB14x_20200612_EN		Date: 2020.06.12
<b>1. Change description</b>		
Change type	Firmware	
Detailed description	Added RutOS Support for TRB14x series gateways	
Change reasons	Until now different TRB series gateways had their own FW version depending on LTE module. After this update FW will become common to all TRB14x gateways.	
<b>2. Affected products information</b>		
Model	Affected order codes	Order code changes
TRB14x	TRB14x *****	No changes
<b>3. Change impact</b>		
Risk Assessment	Migration from TRB14x0_R_00.01.06.1 or older requires Legacy firmware RutOS v2.3 includes Basic and Advanced modes, so some functionality may appear missing until Advanced mode is selected.	
Risk Assessment	Special preparations are unneeded.	
<b>4. Acknowledgement of PCN Receipt</b>		
If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above.		