



## 2024.12.19: Tamper evident sticker

Beginning in January 2025, RUTX11 devices will be packaged in a box with a tamper evident sticker.

PCN Number: PCN\_RUTX11\_Tamper evident sticker\_2024.12.19\_EN

Change description	
Change type	Packaging changes
Detailed description	<p>RUTX11 devices will be packaged with tamper evident sticker on the box.</p> <p>Please note that this change will be implemented gradually, throughout a 3-month transitional period starting in January 2025. During this period, your shipments of RUTX11 may consist of either the current packaging or the new one described above.</p>
	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Seal on:</p>  </div> <div style="text-align: center;"> <p>Seal removed:</p>  </div> </div>
Change reasons	To enhance security and ensure reliability by confirming packaging integrity.

Affected products information		
Model	Affected order codes	Order code changes
RUTX11	RUTX11 ***** (For North America region order codes)	N/A
Upcoming change date	2025 January	

Change impact	
Risk assessment	<ul style="list-style-type: none"> <li>The sticker may leave residue on the box, affecting the packaging's appearance.</li> <li>Marketing material such as photos might need replacing.</li> </ul>
Suggested implementation plan	Information included in this PCN will help adapt to the upcoming changes. For more detailed information, please contact your sales representative.

**Acknowledgement of PCN receipt**

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above